



NEX_TASK

NEXTASK SOLUTIONS



Task Information

Form Name Site Survey_GLI

Uploaded By Kamran Khan

Server Date 2023-04-02 10:43:25

Reference ID c324915b-da34-4ded-9ef6-d7ca9d1d6e6a



Work Order Information

Task ID PA20230329000100

Site ID RIY0023

Title site survey

Region Region_2

Area riyadh

Policy Name Site_Survey



Work Order History

Dispatched 2023-03-29 13:19:22

Delivered 2023-04-02 00:01:00

Accept 2023-04-02 08:41:06

Departed 2023-04-02 08:41:19

Arrived 2023-04-02 08:41:22

Processing 2023-04-02 08:41:32

Completed 2023-04-02 10:43:25






Photo for the site from outside showing the complete site from 3 locations (2 corners and 1 center)



2023-04-02 08:42:11
24.7523 46.5791
RIY0023
PA20230329000100

Photo for the site from outside showing the complete site from 3 locations (2 corners and 1 center)



2023-04-02 08:42:26
24.7524 46.5791
RIY0023
PA20230329000100

Photo for the site from outside showing the complete site from 3 locations (2 corners and 1 center)



Panorama Photos from bottom of tower showing all directions toward outside



2023-04-02 08:43:02
24.7523 46.5792
RIY0023
PA20230329000100

Panorama Photos from bottom of tower showing all directions toward outside



Panorama Photos from bottom of tower showing all directions toward outside



2023-04-02 08:43:28
24.7523 46.5792
RIY0023
PA20230329000100

Access Road status/Photo

2023-04-02 08:45:17
24.7524 46.5790
RIY0023
PA20230329000100



Site road type/Photo



2023-04-02 08:43:47
24.7523 -46.5791
B40023
MA20230229000100

Any obstacles during access the site/Photo



2023-04-02 08:43:59
24.7523 46.5791
RIY0023
PA20230329000100

Site surrounding garbage/Photo

2023-04-02 08:44:09
24.7524 46.5791
RIY0023
PA20230329000100




Risks on citizens around the site/Photo



Building height/Photo






Shelter No.1/Photo



Type of shelter No.1/Photo



No. of additional cabinets that can be installed



Photos for all installed indoor telecom equipments/Photo



Photos for all installed indoor telecom equipments/Photo





No. of modules for Rectifier No.1/Photo



No. of free slots for Rectifier No.1/Photo



Battery No.1/Photo



Battery No.1 Capacity (Ah)/Photo



Fire panel availability/Photo











Tower structure status/Photo



Tower Member status/Photo



Tower foundation status/Photo



Tower galvanization(No rust appear)/Photo



Tower Ladder status/Photo




2023-04-02 09:52:18
24.7523 46.8791
RY0023
PA20230329000100


Tower bolts connections & welded connections/Photo



Tower Verticality Status/Photo




Tower Paint Status/Photo





2023-04-02 09:52:52
24.7523 46.5791
W0023
W00230329000100


Lightning Arrestor Status and Connectivity to Earth Pit/Photo



Safety wire/Rail status/Photo



Site Access ladder status/Photo



Cap lock for safety rail/wires/Photo



Aviation Warning Light Status/Photo



2023-04-02 09:25:52
24.7523 46.5791
RY0023
PA20230329000100

Main Gate Condition/Photo



Fencing System Overall Assessment (if applicable)/Photo




Fencing System Overall Assessment (if applicable)/Photo



Sign board (Site ID)/Photo




RF Cable Trays Overall Assessment/Photo



Soil compaction status/Photo



Wires status assessment for wired sites/Photo




Cable tray gantry post status/Photo



Cable tray post foundation status/Photo




Cable tray free space for cables/Photo




Double nuts status for anchor bolts/Photo




Concrete blocks status for Non-penetrated RT site/Photo



Concrete blocks count for Non-penetrated RT site/Photo



Any installed counterweight status/Photo






Mount fixation with the wall in the wall mount sites/Photo



2023-04-02 09:57:34
24.7523 46.5791
RIY0023
PA20230329000100



Shelter Beam or foundation status/Photo



Shelter body status/Photo



2023-04-02 09:58:03
24.7524 46.5790
RIY0023
PA20230329000100

Shelter roof status/Photo




2023-04-02 09:27:01
24.7523 46.5791
RIY0023
PA20230329000100

Shelter door status/Photo



Shelter floor status/Photo




Shelter Stairs/Photo






Panorama pics for all installed sectors from down/Photo



Panorama pics for all installed sectors from down/Photo



Panorama pics for all installed sectors from down/Photo



Tower load status/Photo



Tower load status/Photo



Cable ladder status for expansion/Photo




Site Security Overall Assessment/Photo






Site Pipes and Conduits Overall Assessment/Photo



Junk Materials & Unused part in Site Area/Photo



Main electricity panel status/Photo




Power Meter status/Photo



All power cables connection status/Photo





ATS fixation and isolation status/Photo







Generator pipes connections status/Photo



Generator foundation status/Photo



Fuel tank and its foundation status/Photo



Generator oil leakage/Photo



Generator fuel leakage/Photo




Check the whole Power cube system is ok or not (Generator swapped with batteries) /Photo



Need to check the active alarms on SMU which are reported to NETECO system (Check and configure all disable alarms)/Photo



Check the Function Module ESMU-02A/Photo



External Lighting status/Photo



2023-04-02 10:04:31
24.7523 46.5790
RIY0023
PA20230329000100


Door sensors status/Photo







Phase Failure Relay & Status/Photo










Shelter cable ladder status/Photo



Environmental alarms status/Photo





Alarms On Rectifier screen/Photo



Rectifier modules status/Photo




Rectifier connections status/Photo




Rectifier redundancy status/Photo




Rectifier Door and cabinet/Photo



Rectifier Surge Arrestor/Photo



Rectifier Batteries Temperature Sensor/Photo




Batteries status/Photo











HVAC panel status/Photo



Fire panel status/Photo



Fire extinguisher status/Photo




Smoke/fire & Heat sensors status/Photo



Internal Lighting/Photo





Any obstacles during climing the towers/Photo


















































2023-04-02 09:00:13
24.7524 46.5789
RIY0023
PA20230320000100




























RRU and MW radio are occupying special mount or Same mount/Photo







Link No.1 configuration/Photo







Link No.2 Vendor/Photo






Link No.2 configuration/Photo



MW Antenna No.2 Main size/Photo







Link No.3 configuration/Photo



MW Antenna No.3 Main size/Photo





2023-04-02 09:32:07
24.7523 46.5784
RIY0023
PA20230329000100




Link No.4 configuration/Photo




MW Antenna No.4 Main size







Link No.5 configuration/Photo



MW Antenna No.5 Main size/Photo




Unused /unconnected Equipments on tower/Photo















































































Tower No.1 Structure/Photo




RT Tower height from Roof level/Photo



Drilling on Tower structure specially for MP or LP sites/Photo







Parapet with low height in RT sites/Photo




Free Area inside Fence (m²)/Photo




2023-04-02 09:41:42
24.7523 46.5791
RIY0023
PA20230329000100

Free Area inside Fence (m²)/Photo









2023-04-02 09:44:32
24.7523 46.5791
RIY0023
PA20230329000100



Additional sub meters if any/Photo






2023-04-02 09:45:09
24.7523 46.5791
RIY0023
PA20230329000100



2023-04-02 09:45:22
24.7523 46.5791
RIY0023
PA20230329000100



N.A.

