

Twincur Discontinued/Replacement List March 11, 2015

DISCONTINUED	REPLACEMENT		
4" Twincur GB	CFP Series (4")		
GB40200R	CFP400M		
GB40500R	CFP401M		
GB41000R	CFP402R		
GB42000R	CFP403R		
GB43000R	CFP404R		
	EGV4SNL		

DISCONTINUED	REPLACEMENT	Also available
6" Twincur GB	6" Twincur EB	5" Twincur EB
GB60100R	N/A	N/A
GB60200R	EB60200R	EB50200R
GB60500R	EB60500R	EB50500R
GB61000R	EB61000R	EB51000R
GB62000R	EB62000R	EB52000R
GB63000R	EB63000R	EB53000R

DISCONTINUED	REPLACEMENT	Also available
5" Twincur EG-S	5" Twincur GEM	6" Twincur GEM
SNL50080	GEM50100	GEM60100
SNL50150	GEM50200	GEM60200
SNL50300	GEM50500	GEM60500
SNL50500	GEM51000	GEM61000
SNL51000	GEM52000	GEM62000
SNL52000	GEM53000	GEM63000
SNL53000	GEM5TSUYA	GEM6TSUYA

DISCONTINUED	REPLACEMENT	Also available
5" Twincur EG-V	5" Twincur GEM-V	6" Twincur GEM-V
EGV50080	GEV50100	GEV60100
EGV50150	GEV50200	GEV60200
EGV50300	GEV50500	GEV60500
EGV50500	GEV51000	GEV61000
EGV51000	GEV52000	GEV62000
EGV52000	GEV53000	GEV63000
EGV53000	GEV5TSUYA	GEV6TSUYA
	EGV5SNL	EGV6SNL

The above discontinued items have limited stock and will continue to be sold until the stock is depleted.

If you have any questions or need additional information, please visit our website at www.alpha-tools.com or contact your sales or customer service representative at (800) 648-7229.