Ship or Vessel in Service Name: CORNWALL

Dated: 6 December 2012. Where lying: PORTSMOUTH UK



Picture for illustration only

Contents

Section 1
General particulars
Hull and Structure
Deck Gear
Machinery and Systems
Documentation
Stability and Ballasting

Section 2

Inventory of Potential Hazardous Material on Board (not included - under revision)

General particulars

Data and Diagram (D. 11)	General particulars		
Date and Place of Build	1988 Yarrow Shipbuilders, Glasgow UK		
IMO No.			
Date ceased service	20 October 2011		
Type of Vessel: Official No.	Formerly a Warship - Frigate:		
Ex Pennant No.	F99		
Summary of condition	Sound for Towing, not in running condition, certain equipments, having		
	been removed by MoD for further use.		
Displacements and tonnage in	Current: 4753		
Tonnes	Normal: 5077 te		
	<u>Designed</u> Lightship weights:		
	Hull and General fittings including hull structure (1166 te) and		
	electrical (185 te) = 2131 te		
	Not including		
	Other equipments 232 te*		
	Machinery 682 te*		
	Armaments 273 te*		
	* Note: MoD has removed some items for re-use		
	Additional Lead solid ballast Approx. 150 tonnes§		
	§ Note – reported in datum pack - this figure is not guaranteed		
Draughts	Current: Fwd 3.8. Mid 4.2 Aft 4.6		
Length OA and Waterline	Extreme: 148.1m. WL: 136.32m		

Breadth	Extreme: 14.75m
OA height Mast-head to keel	30.2m
Last Docking	2008 Plymouth
Last Refit	2004 Plymouth

Hull and Structure

Propeller	Twin Controllable Pitch (CPP) 5 bladed skewed propellers, 2.5m diameter
	with approx 3.2m length bosses. Manganese bronze. Nil bow thrusters.
	Props project (prop sweep) 1.3m below line of keel.
Shaft & Gland	Twin shafts, turning gear in, brakes on. Glands hard up and dry.
Rudders	Twin. Mechanically and hydraulically locked amidships.
Stabilisers	4, two each side, projecting 3.2m at a downward angle (1.55m
	perpendicular). Hydraulically and mechanically locked.
Logs	1, electromagnetic type. Projecting 0.47m from outer bottom.
Sonar	2 separate hull mounted sonars projecting 2.26m and 0.8m from outer
	bottom respectively.
Keels	2 bilge keels projecting approx 1m from outer bottom round-down.
Hull valves	Shut and wire locked.
Hull condition	Sound at last docking (2008).
Paint coatings condition	Non TBT
UW hull:	Good. Weed growth evident.
Upper hull:	Appears in good condition.
Superstructure:	Appears in good condition though paint coating has been heavily disrupted
	and light corrosion is now evident.
Accommodation	Bulk of soft furnishings have been removed, carpets remain.

Deck Gear

Dook Goal	
Anchors	Foc'sle. 1 Bow anchor – removed to facilitate towing cable. 1 Sheet anchor made up for letting go – Admiralty pattern AC14. Weight is 1960 kg. Housed and stowed.
Chain Cable	Bow is 9 shackles (247.5m), in use for mooring and towing purposes. Sheet is 7 shackles (192.5m) made up for letting go. Both are 38mm dia chain link. Both are out of certification.
Towing	Partially rigged from recent tow. Further preparation and final approvals are required.
Cordage	Some remains, none is certified for use.
Bollards/Bits	Appear sound
Davits/Cranes	Davits and Boat launching cranes inoperative.
Boats	Removed, nil remain
SOLAS	None

Machinery and Systems

Boilers	2 Stones Vapours
Main Engines	3 gas turbines removed, only one remains
Generators	4 Paxman Valenta 12 RPA200 450v 60 Hz 1000kw. Not maintained.
Auxiliaries and Pumps	Electrically driven. Not working.
Electrical	440v 60Hz and 115v 60Hz. Not safe for use, system is cut.
Steering Gear	Hydraulically and Mechanically Locked.
Electronic & Sensors	None working.
GMDSS	None
Batteries	Removed.
Fire-Fighting	Not working or maintained.
Sanitary	Sewage Treatment Plants. Empty and cleaned.

Documentation

Certification	Anchors and cable: not in date.
Drawings – Main	SOME
Operating Manuals	None
Historical	None

Stability, Ballasting and Tank Contents

otability, ballasting and Tank Contents	
Ballasting Summary	932.3 tonnes fresh water ballast in main fuel tanks which were emptied and
Tanks State	cleaned prior to ballasting. Remainder of tanks empty and cleaned apart
(See DLS Form1 Encl. 13).	from residual in smaller tanks, CPP and Steering Gear remain charged with
	hydraulic oil.
Stability Summary	Stable. Stability for tow is subject to confirmation by new owner.
Signed	Signed on Original
Representing	Disposal & Reserve Ships Organisation
Date	6 December 2012