

0805 S - 91 designated M - 91 Possible Argentinian Auxilliary
FCS (Average) 260/10 kyds 130/14 ACB 50 Port

0810 C/S 18 to close M 91

0836 M91 FCS (Good) 100/0.8 kyds 115/15.5 A0B 175 Starboard TPK = 11.3
Initial detection range Passive LF 112 kyds
Audible Sector 78 kyds
SSS 3 - 4

0845 CO COMIENT

I am now underneath M91. MLA 115 - 16 knots, which would suggest she has come from around the western edge of Isla de los Estados. Although I am confident she is a merchant ship, I think I will stay with her until sunrise to check and then return to the BELGRANO area.

1113 START EVENT 0401 - VISUAL IDENTIFICATION M91

CO COMMENT

I am in position 55 52.1S 60 55.0W, approximately 40 miles SSE of the BELGRANO datum. I am almost underneath M91. The intention is to go underneath to obtain the best fire control solution, then to open ahead and to the North of her to 1500 yds off track. Once I have confirmed that she has not altered course I shall come up and take a look at her on the port beam, ready to fire in the unlikely event that she is a warship. FCS (Good) 110/0.6 kyds 110/15.5 AOB Right Astern

1125 On top.

1126 C/C 080 C/S 21 to open out

1134 Sunrise

1136 DOT now 1400X C/C 100


1141 C/D PD C/S 6 C/C 000 to look at M - 91

1144 CO COMMENT

M - 91 visual description. Red hull, Pennant number B1. Unbroken deck line. Two superstructures with well deck in between with crane. Helo deck aft of second super structure, which must be a hangar. No helo on deck. Both superstructures White Large Red Cross on after White Superstructure. Very short focsle.

SECRET B-78





1145 · Taking photograph of M - 91
Nothing else visual


1148 C/D 260

1149 END EVENT 0401
CO END OF EVENT SUMMARY

 $\rm M - 91$ believed to be the BAHIA PARAISO being used as a $h_{\rm espital}$ ship.

Intelligence gained a. TPK 11.3

b. Fennant number B1



B - 080 - S92) B - 099 - S93) All sector contacts, no classification

B - 080 - 594)

202 Warner clearance. No Rackets
M - 91 has a helo ranged on deck, possibly Jet Ranger type

206 M - 91 only contact held sonar. All others have faded

214 E 99 No bearing PW1.1 PRF 432 No ARP - No classification but not airborne

218 B - 070 Aircraft far - P ssibly 707 - commercial airliner type of plane

B - 090 S93 regained

B = 095 S 93.2 X 3 80 revs - Possibly a Summer Class Destroyer?

230 S - 93 faded

UK EYES 'B'

B-79





B - 084 R - 8 kyds Helo in sight

CO COMMENT

I have seen the Hospital Ship and her helicopter a fixed wing aircraft probably a 707 and smoke from S93. This could well be an SAR operation, but the position is 40 NM 140 from where I attacked the BELGRANO.

The 707 appears to be flying a N/S race track 15 NK to the SE of me

Weather Wind: Light airs Vis 7 NM Seastate 1 from 248 SSS 2

Cloud 55%

C/D 260 C/C 090

M - 91 FCS (Average) 112/9 kyds 110/15 AOB 178 Port

32 C/D PD

328

B - 070 Aircraft R - 10 kyds C/D 260

B - 098 S92 2 X 3 100 revs Possible Warship Intend to return to PD to identify S 92

START EVENT 0402 - IDENTIFY S92 POSSIBLE WARSHIP

CO COMMENT

In position 55 45.7S 60 20W, I believe S92 is one of the Destroyers (MO3/MO5) and that she is involved in SAR Operations with the BAHIA PARA ISO Intention is to close, return to periscope depth and identify her visually

M 91 B - 105, blanking S92, possibly S92 has stopped or altered course


There are no transmissions


B - 092 S92 2 X 3 92 revs - warship B - 092 S93 ? X 4 144 revs - possibly TUG


CO COME INT

I now have a second contact on S 92's bearing - this is possibly the Tug GURRUCHAGA that is a part of TG 79.3

S92 FCS (Poor) 113/7 kyds 110/6 A0B 177 Port







IN EYES 'R'

C/D PD C/S 6

S - 92 B-118 R-10 kyds

S - 93B - 098 R - 10 kyds

B - 078 R - 7 kyds

E - 91 707 aircraft also visual Masts and smoke (Tug?) BAHIA PARAISO

SUMMER CLASS DD

CO COMMENT

The smoke to the left and beyond S 93 could well be the Second Destroyer

C/D 260 C/S 10 C/C 350

139 END EVENT 0402

CO END OF EVENT SUMMARY

Returned to PD and and identified S 92 as a SUMMER Class DD. is apparent that a full scale SAR operation was being conducted for the survivors of the G BELGRANO

C/S 21 C/C 005 - Heading for TEZ

CO COMMENT

Identified M91 as the BAHIA PARAISO Hospital Ship at Sunrise. She then altered course to NE and launched a small helicopter to join the 707 type aircraft in what appeared to be a search. Closed search area to see who was there. Final look showed:

> A/C - 707 typeSUMNER Class DD Masts that looked like PC GURRUCHAGA Hospital ship and her Helicopter

- Ships were searching slowly East and A/C on a race track N/S. They are obviously conducting a DATUM search. Set from BELGRANO position (now confirmed sunk in COR 193) is 140-1 knot. COR 194 does not allow me to attack warships involved in SAR operations (quite rightly).
- Intentions Open to North at 20 knots. BELGRANO DATUM is being searched by 8 aircraft (COR 193), so I shall give it a wide berth Aim is to go to Position 55S 60 10W on edge of TEZ, take routine and then track WNW looking for Trade.


C/D PD C/S 5 Send SITREP, Routine. Fix and Domestics

Received COR 191 SHEFFIELD Sitrep COR 197

Remain out of DOG 3Q - NGS Ops

COR 199 Protect SHEFFIELD from DD's

C/D 260 C/S 21 C/C 080





CO COMMENT

SHEFFIELD position from F STANLEY carbled in COR 199. Sent a query on channel 5 and received reply on HF within 15 minutes. Intend transitting fast East to edge of area, hopefully to get between SHEFFIELD and DD's

Position 54 49 S 60 03 W

Weather: Wind - light airs

Sea State - 1 from 330

Cloud - 100% Visibility - 4 nm

SSS 3-4

Very calm

SVP: 020 - 4850

200 - 4850

Sunset

In intercept position _ C/S 4 C/C 235 for search

C/S 21 C/C 070 No contacts, off to set up a patrol line across most likely approach route of the DDs.

C/S 4 C/C 290 On the patrol line

CO COMMENT

I have arrived at the SE edge of my Patrol Line and after a careful CSA found no contacts. Since we have a leak (steam?) in the RC, I have decided that now is a good time to conduct a RC entry. Doing just that.

Scrammed for RC entry

CO COMMENT

Steam leak found on starboard SG inboard handhole cover. At first glance this is unrepairable

C/S 8 Continue search on patrol line

CO DAILY SUMMARY

Spent the morning sitting underneath a M/V to see where it was going. At sunrise, came up to PD to identify it as an Argentinian vessel, probably some form of oil-rig/Antarctic support craft which is now a Hospital Ship - Red Cross on the side. From my intelligence signals, it must be BAHIA PARAISO



HK EVEC IN



Established that it, plus the Tug and at least one DD, probably two, were conducting a Datum Search supported by an aircraft and the Hospital Ship's helicopter. Assessed they were looking for survivors and therefore withdrew to the North with the intention of searching along the TEZ boundary. However, while at PD at 1900 - 2000, received COR 199 instructing me to cover SHEFFIELD from attack by the two SUMNER Class DDs. Therefore headed East to set up an AS $_{\pmb{\gamma}}$ Patrol on Eastern Edge of my Area and TEZ.

At 2330 conducted a successful RC entry to discover a steam leak on the starboard SG inboard handhole cover - the implications of which are still being considered.

WEDNESDAY 5 MAY 1982

0100 B - S/NE T - 09 380 Hz line very weak

0105 T - 09 faded

0241 C/D PD C/S 5. Routine, Fix, Domestics and Ventilate

Weather: Wind light airs Vis 2NM

Seastate 1 from 090 SSS 6 Cloud 100% SVP 060 - 484

Cloud 100% SVP 060 - 4847 210 - 4846

0315 Ventilating

O415 Stop Ventilating
C/D 260 C/S 8.C/C 120
COR 196, 200,201 received

CO COMMENT

Ventilated for one hour, close up with traffic, going deep for ASV patrol. Vis 3000 yds


0800 Position 54 41.7S 59 13.5W


0900 B - 234/006 T - 10 Either a slow diesel or blade rates indicating 220 rpm


0916 C/C 260 CSA and resolve ambiguity on T - 06


0935 T - 06 B - 230

0945 T - 06 faded









Part 5

UNCL**AS**S/NPM

UK EYES 'B'

1005 C/D PD C/S 5 Routine, Fix and Domestics

CO COMMENT

I have been at PD for 40 minutes trying to receive traffic. HF is no good.

I believe SHEFFIELD is probably no longer worth covering therefore I am moving away and down to the SAR Datum looking for the DD's.

1045 C/D 260 C/S 8

1124 Sunrise

1135 C/C 320 SAC

B - 220 S34 faint aural

1148 C/C 220 to close S34 C/S 12 (Maximum holding speed)

1155 B - 220 S 34 1 X 4 102 rpm

1240 CO COMMENT

I hold a contact, faint at 218 - closing at 12 knots, probably Non-warship

t325 <u>CO COMMENT</u>

Best estimate of range on S34 approximately 50 kyds as none of my ranging manoeuvres have had any effect on the bearing rate.

1346 B - 219 S - 34 is possibly 2 contacts on the bearing. 7.3 Hz diesel signature spacing is similar to M - 91's yesterday

CO COMMENT

From the GOP, these contacts could be in the search datum

1355 C/D PD C/S 6 for Routine and Fix

1455 CO COMMENT

Routine received COR 204 - Open Season again on the DD's, and two groupers of 325 and 750 each = FRUSTRATION. C/D 260 C/S 16

SECRET UB-85ES 'B'

UNCL**AS**S/NPM

UNCLASS

JIK EYES 'B'

1507 · B-214~S-53~1~X~4~150~rpm, possibly small M/V

CO COMMENT

S53 classified from gram as M - 91. Hospital Ship S34 DD and Tug

CO COMMENT

I think these contacts are approximately 20 kyds away - but they are still confused, making identification very difficult. is close the range, return to PD and identify them.

START EVENT 0501 - IDENTIFICATION OF \$34 AND M91

CO COMMENT


In position 55 09S 6032W. Having closed the datum from the North looking for the Destroyers, I have a confused sonar picture and need to return to FD to clarify what each contact is - in fact I think there may be more than one ship on S34's bearing.

Possible transmissions heard on 185, right astern (B - 050) Possibly 12 Khz on Watcher, no bearing (Set a 6 dBs)

CO COMMENT

If these are 12 kHz transmissions they would be from the SQS 30 in the DD's. However the best bearing on 185 is from M91 which I assess to be at a range of 5 kyds. If they did come from M91 they would be deflecting Watcher so I feel that they are either:

- Not transmissions or
- From the DDs who are far away and not held sonar
- M91 FCS (Average) 038/10 kyds 030/14 172 Stbd S34 FCS (Average) 257/17.5 kyds 240/14 162 Port C/D PD C/S 5
- At PD Vis is only 3000 yds. Nothing Visual





UK EY S 'B'

636 ' END EVENT 0501

CO END OF EVENT SUMMARY

Believe M91 is a M/V - possibly doing 030 - 14 and making a lot of noise to be a Red Herring?

S - 34 I believe to be a Warship heading SW. Intend going deep and fast to overtake her. It was most frustrating to arrive at periscope depth and not be able to see either contact because of bad visibility.

CO COMMENT

- 1. Inspection of gram shows M 91 is not the Hospital Ship BAHIA PARAINO. Could possibly be the AO PUERTA ROSALES, shaft rate is very similar.
- 2. It has taken 3½ hours to receive and then decrypt COR 202 I wonder whether the person writing 'BAD JINGLES' would be so keen if he had to try and decrypt them. I regret my sense of humour does not stretch that far. However only my first sense of humour failure with my Controller!
- M 34 FCS (Poor) 294/30 kyds 320/14 AOB 154 Port Indicates possible 5 blades and looks more like a M/V now.

CO COMMENT

My 1630 thought that M34 was going SW was wrong. She is apparently heading for the Eastern edge of the Isla de Los Estados. The problem is not helped by the new sound room classification of Merchant Vessel instead of Warship. However I believe whoever it is is going fast (greater than 18 knots) as I am not sure I am closing and I am doing 23 knots. Intend running for a further hour and then reassessing the situation. Vis up top last time was only 3000 yds which does not help.

M34 FCS (Average) 300/3 kyds 290/17 A0B 170 Port

M - 34 B 300 - 1 X 4 108 rpm M/V S - 60 (Hindsight) 1 X 5 90 rpm M/V

CO COMMENT

M - 34 now appears to be two contacts! I shall sort out both FCS and when happy, return to PD to identify them. I'm certain M34 is a M/V and I think S60 may well be a side lobe.





745

715

800

1007

908

UNCL**AS**S/MPM

IK EYES 'B'

1910 M - 34 on top

C/C 180 to look for S - 60 astern 1918

No contact

C/C 320 to look for S - 60 to the North of me - Nothing 1921

1930 C/D PD C/S 6 M34 FCS(Good) 302/2.5 kyds 270/14 A0B 145 Port

CO COMMENT

M - 34Modern supertanker fully laden White superstructure right aft, black hull 2 King Posts 3 from bow Operating her radar Up sun so could not see her name

Visibility is now 12 NM!

Warner clearance

B - 272 E - 62 I Band (N - 34)

B - 310 E - 63 E/F Band Nothing visual that bearing B - 272 E - 62 I Band COMNAV E - 63 is a side lobe

2000 Position 55 05.3S 61.22W

> Weather Wind 5 knots from 000 Vis 12 NM

Seastate 1 from 000 SSS 3

SVP 020 - 4850 Cloud 20% 200 - 4850

CO COMMENT

Will remain at PD for routine and fix. M34 was a modern tanker with 1 X 5 and a TPK of 5 Her modern screw made her sound like a warship

2008 C/D 260

2033 Sunset

2148 C/D PD C/S 5 Routine and Fix


C/D 260 C/S 21 C/C 330


CO COMMENT

Heading to a patrol line inside TEZ between Isla de los ESTADOS and BURDWOOD Bank

C/S 4 Start Search

UK EYES 'B





B - 155 S01 17806 - 1793.8 unstable discrett frequency Investigating

B - 151 SO1 now held pastive C/C 145 C/S 7 to close

2343

B - 149 SO1 Faint aural - M/V

C/D 200 C/S 3 - slowing down to catch a trim prior to RC Entry

CO DAILY SUMMARY

Ventilated for one hour overnight to save 02 Candles. At 1455 I received COR 204 which allowed me to attack DD's again. I had already been moving down to the SAR position. Holding one or more contacts to SW I was closing fast when at 1600 one contact started to move From then until retur ing to PD at 1937 I was confused. I ran after the contacts going West as sonar initially thought there to be a warship there. Return to PD showed there to be one Tanker. I hope the warships did not proceed to the NE with N - 91 at 1600. The evening was spent moving up to the western edge of BURDWOOD Bank to continue search.

MURSDAY 6 MAY 1982

0016

Scrammed for RC Entry

Reactor Critical

CO COMMENT

Second Reactor entry. This time to attempt to divert the water leaking from the handhole cover away from the Primary Coolant lagging. Successful we believe.

C/D 280 Continue ASV Patrol

215

C/D PD C/S 5 Routine, Fix, Domestics and ventilate

Weather Wind: Light airs Seastate 2 from 050 Vis 8 NM SSS 3

Cloud

45%

Long grouper coming in on HF



HK EYES 'B'

0301

B - 050 E - 62 Dangerous: ANAPS 20

Stop Ventilating C/D 260 C/S 20 C/C 324

CO COMMENT

- Went deep Racket came straight up as dangerous. but believe he was on surface search rather than ASW. as I was ventilating I am clearing the area at speed for 1 hour.
- Heading north in response to garbled COR 205/206. Something brewing up there?
- COR 205 Reports that BOUCHARD may be at or en route to USHVAIA to recover from storm damage - not that we have been in a storm. BUENO may be enroute there with condenser problems. I can't reach them and furthermore they are no longer an immediate threat to TG 317.8: I hope we meet again!

0800

Position 53 37.4S 62.23.1W

SSS 4

SVP 020 - 4860

200 - 4860

0908

C/D PD C/S 5 Routine, Fix, Domestics and ventilate

0922

Ventilating

1028

Stop ventilating

CO COMMENT

Ventilated for 1 hour. CSA and then off to Western Edge of TEZ to continue ASV Patrol

1040

C/D 260 C/S 19 C/C 285

1127

Sunrise

1535

C/D PD C/S 5 Routine, Fix and Domestics

Vis 5NM

Weather: Wind force 2 from N

Seastate 1 from N


SSS 4 - 5


Cloud 100%

SVP 020 - 4851


220 - 4854

C/D 200 C/S4 Continue ASV Patrol





OGOOO - OTOOOO UNCLASS/NPM



UK EYES 'B'

UNCLASS/NPM

C/S 11 C/C 320 Heading NW to continue patrol

52 44.3S 63 46.4W 2000 Position

2046 Sunset

C/D PD C/S 5 Routine, Fix, Domestics and ventilate 2128

Ventilating 2145

2245 Stop ventilating

C/D 260 C/S 11 2310

CO COMMENT

On going deep we cavitated at 260 feet and 11 knots. This is shaft Investigation found no internal cause. Possibly interaction between shaft/tow staff which has been heard before. It is made more evident by low SSS. Assessment suggests it is more a shaft rub than cavitation and comes in at 65 revs.

C/D 280 C/S 9 C/C 065 Continue ASV Patrol 2350

CO DAILY SUMMARY

A quiet day searching my area making towards the NW looking for trade

FRIDAY 7 MAY 1982

0054 B 237/263 T -12. 263 Hz gearing line.

01 03 C/C 350 to resolve ambiguity

B - 263 T - 12 Ambiguity resolved 0118

CO COMMENT

This line is a very weak and somewhat unstable gearing line


خ * 0346 C/D PD C/S 5 Fix and Routine Vis 6NM Wind: Light airs SSS Weather

020 - 4856Seastate 1 from 035 SVP Cloud 70% 100 - 4865

220 - 4864

340 - 4860

UNCLASS/NPM



0459 C/D 260

CO COMMENT

Have spent 1 hour at PD receiving traffic. Am close up on BILAT but there is a grouper coming through on HF. Reception is ZBZ 2 and from the DTG, this signal must be COR 219 - Not vital for me. Going deep to continue the search

0800 Position 51 51.7S 62 52.3W SSS 1 - 2 SVP 020 - 4873 200 - 4875

C/D PD C/S 5 Routine, Fix, Domestics and Ventilate

CO COMMENT

Completed my hours ventilation and received all traffic. Intend searching to NE which will cover the West of the Islands.

1128 Sunrise

0857

1526

C/D PD C/S 5 Routine and fix
Weather - Wind 10 knots from 090 Vis 7.5NM
Seastate 1 from 090 SSS 3
Cloud 100%

1554 START EVENT 0701 - PROBABLE COUNTER DETECTION BY AIRCRAFT

CO COMMENT

In position 51 23.7S 62 14.7W at PD taking my routine with the Search Periscope and Warner mast raised. Sea and swell were slight and the visibility was 15000 yards. I had been at PD for 30 minutes.

1554½ B - 050 R - 2kyds Aircraft (Possible NEPTUNE)

Visual: flying SSW

B - 330 E 53 I Band 1/10 PRF 951 PW 0.9 ARP 2.4

C/D 600 C/S 21 C/C 090 (magnetic East)

ACTION STATIONS, Shut off for Attack and Counter Attack

OOW COMMENT

Aircraft was very low and flying almost parallel to own course. Weapon load, state of bomb doors were not observed. Visual identification - possible NEPTUNE/CANBERRA E - 53 classification a. (978 (YARMOUTH) - ?!)

b. Out of parameter 1. ANAPN 59 - C130 HERCULES

2. AIDA2 - MIRAGE

c. It could not have been an ANAPS 20

CECDET



1556 Aircraft trace on towed array

CO COMMENT

Aircraft has overflown me

1559 B - Port Quarter, on watcher and passive. Fast moving contact.

CO COMMENT

Possible Torpedo dropped by aircraft

CO COMMENT

CO COMMENT

1615 END EVENT O701
CO END OF EVENT SUMMARY

Had just received a FLASH (COR 224) saying a NEPTUNE was in the area. OOW saw an aircraft close and low, flying up the Port Side, not flying in. Went deep and went to Action Stations, Shut off for Attack and Counterattack. At the same time E - 53 was reported by WARNER. Shortly afterwards aircraft trace was seen on towed array, followed by fastmoving contact on Port side on Watcher.

My assessment was that we had been 'bounced' by a NEPTUNE, who might have dropped a Torpedo. Went Full Ahead to evade to the South.

Full Ahead was used to prevent a possible scram if Torpedo had detonated close to submarine. The Battle Short was made for 14 minutes.


In retrospect, although overflown by an aircraft (NEPTUNE?) and therefore probably counterdetected - Racket was not ANAPS 20 - WATCHER Contact was not a torpedo

SECRET OK EYES 'B'

UNCL**AS**S/MPM

SECRET

UK EYES 'B'



CO COMMENT

Whilst I was at PD COR 223 received changing overall ROE (11/82) depending on area. Not mine as I am in the TEZ. Intend remaining deep until I am over xxxxx from the datum before I return to PD.

654 C/D 300 C/S 12

1830 CSA C/C 150

CO COMMENT

2000 Position 52 07.3S 61.59W SSS 2

2039 Sunset

2128

C/D PD C/S 5 Routine, Fix and Domestics
Weather Wind 15 knots, direction unknown
Seastate 2
Cloud 50%
SVP 020 - 4863
200 - 4863

CO COMMENT

At PD for routine and to pass my Sitrep. 60 NM SSE of Datum. Still good vis, but too dark for an aircraft to see me. Nothing in sight.

One new signal (COR 225) ROE 12. Doesn't affect me


Intend making ground to West overnight


2213 C/D 26 C/S 11 C/C 280

2359 CO DAILY SUMMARY

A quiet day on patrol in Area - with the exception of the aircraft possible/probable counter detection at 1554. Seastate has increased and our "shaft associated" noises have gone away.

SECTION OF THE PROPERTY OF THE





HK EYES 'R'

UNCLASS/NPM

SATURDAY 8 MAY 1982

0001 CO COMMENT

Overnight intentions are to take 0300 and 0900 routines and make ground to the West to patrol Western edge of area in daylight

0325 C/D PD C/S 5 - Routine, Fix and domestics

0455 C/D 260 C/S 4

CO COMMENT

Another $1\frac{1}{2}$ hours at PD trying to receive my traffic on HF and SSIXS - intermittent reception on both. One signal is 1194 groups, 6 short of the maximum allowed! It must be important as the Controllers know what problems I have (Later: 1194 groups = COR 226, SITREP on ARG Forces).

COR 229 - ROE 13/82 - Does not change my ROE

0800 Position: 52 16.6S 63 09.5W

Weather: Wind 15 knots from 120 Vis 6 NM

Seastate 1 from 120 SSS 2

Cloud 100% SVP 060 - 4855 260 - 4854

0915 C/D PD C/S 5 Routine, Fix and Domestics

1000 Visibility to West - 1500 yds

1015 CO COMMENT

Routine complete. 3 new signals Going deep to continue the search

1018 C/D 200 C/S 11

1141 Sunrise

1509 C/D PD C/S 5 Routine and Fix

Weather: Wind 15 knots from 090

Seastate 1 from 090

Cloud 100%

Vis 6 NM SSS 6

UNCLASSINPM

SVP 020 4877

100 4880

160 4883

CO COMMENT

At PD in a seagull high density area. Vis good. Slight sea - in our favour

SECRET

B**-**98

UK EYES 'B'

UNCLASS/NPM

UK EYES 'B'

1640 C/D 200 C/S 10 C/C 000

2000 Position 51 05S 63 15.5W

2041 Sunset

2117 C/D PD C/S 5 Routine, Fix and Domestics, Ventilate

2119 Too light to ventilate

2220 Ventilating (dark now)

2250 Stop ventilating. C/D 300 C/S 10 C/C 260 (Magnetic West)
Possible aircraft marking on towed array (71 down to 64 Hz)

2256 C/S 5

2300 C/D 200 C/S 11

2307 C/D 380 - line regained on towed array; all beams (72 down to 63 Hz)
Depth of water 500 feet

2310 CO COMMENT

Two possible solutions:-

- 1. MPA on ASW Patrol detected us on JEZ and descended low to localise by MAD
- 2. 2 X Aircraft on low level flight to FI to deliver stores

However:-

- a. Are they that good? No torpedo drop, why not?
- b. No report on our last encounter. Good intelligence has not suggested any ASW activity in my area.
- c. Intelligence reports that aircraft are blockade running to the FI's and we are on the direct route from CABO BLANCO area.

Conclusion - 2 - most probable, 1 - most dangerous

CSA - line not regained

CO COMMENT


Intend moving away to West to continue ASV Ops. Now in shallow water (470 feet) in falling Sonar Sea State (4 at present)

c/p 260

CO DAILY SUMMARY

A very quiet day with no activity except for our over flight above.

SECRET UNCLASS/NPM



SUNDAY 9 MAY 1982

0114 T - 13 B - 290/070 Diesel signature with 3.65 Hz spacing

0118 T - 13 faded

0135 T - 13 regained

0140 C/S 8 C/C 230 to resolve bearing ambiguity on T - 13

0150 T - 13 B 300 Faded

0315 C/D PD C/S 5 Fix, Routine, Equalise Vacuum

Weather: Wind 10 knots from 045 Vis 3 NM

Seastate 2 from 045 SSS 5

Cloud 100% SVP 020 - 4866

090 - 4868

180 - 4869

260 - 4869

0355 C/D 260 C/C 180

CO COMMENT

No traffic for me (- it is Sunday morning!)

0800 Position 51 40 N 63 45.3W

SSS 6+

0908 C/D PD C/S 5 Routine, Fix, Domestics and Ventilate

0915 Start Ventilating

1003 Stop Ventilating

1016 C/D 200

CO COMMENT

COR 237 received - My request for short groupers noted.

1129 Sunrise

1305 C/D PD C/S 5 Routine, Fix and ESM Search

Weather unchanged

SSS 3 - 4

SVP 020 - 4857


100 - 4860

150 - 4860

SECRET

WK EYES 'B'
B-1 01

UNCL**AS**S/NPM



1310 · <u>CO COMMENT</u>

Intend staying at PD for 1 hour for ESM Search, but I think deep gives greater sonar coverage

1330 CO COMMENT

COR 239 received ordering me to shift area to North of FI to get between CVA and our own surface forces - Distance is 430 NM

1410 C/D 240 C/S 17 C/C 005

2000 Position 50 00.5S 62 55.8W

2147 Sunset

2114 B - 280 S - 56 2 pens HF

Very fast left Bearing Rate

2117 C/C 240 - Look for S - 56

2121 3 X Tx's Position 13 Scale 10. No contacts

2122 B - 235 S - 57 2 pens HF

Very fast right bearing rate

2125 C/C 270

2127 3 X Txs Position 13 Scale 10 - No contacts

2129 C/C 030

2135 3 X Txs Position 13 Scale 10 - No contacts

2136 C/D 250

2145 C/S 15 C/C 040

CO COMMENT

I do not think either 8.56 or S-57 were submarines. Intend clearing datum (49 48S 62 38W) for one hour before I return to PD to be absolutely safe.


2301 C/D PD C/S 5 Routine, Fix, Domestics and ventilate

Weather - too dark

SSS 3 - 4 SVP 060 - 4861


180 - 4863

220 - 4865



UNCLASS/NPM





2359 CO DAILY SUMMARY

A quiet morning searching my area until 1300 when COR 239 told me to shift area 430 NM to the North to replace Point Two who is withdrawing for defect rectification. Second half of today spent transitting North with the only excitement being the S - 56 at 2114.

MONDAY 10 MAY 1982

0005 Stop ventilating

C/D 260 C/S 21 C/C 060 0035

Position 47 46S 59 47.5W 0800

C/D PD C/S 5 C/C N Routine. Fix. Domestics and Ventilate 0827

Wind: 15 knots, no direction Vis 2NM

Seastate 2, no direction SSS 5 SVP 020 - 4867 Cloud 100 %

> 130 - 4865300 - 4855

0845 CO COMMENT

I have a Loud interference on I Band WARNER I will only be able to detect I Band Rackets aurally; ie I cannot hear a TRACKER's ANAPS 88 until it is dangerous Intention is not to ventilate until the WARNER problem is resolved

C/D 300 C/S 21 - Head for Patrol area 0935

1111 Sunrise

B - 320 S - 62 Passive Contact 1125 C/S 20 C/C 310 to close

1300 B - 322 S - 62 Range greater than 50 kyds

B - 314 S - 62 Faint trawl noise 1400

CO COMMENT

S - 62 could be part of the Soviet/Warsaw Pact fishing fleet known However, ARG Warships could use them for to be in this area. Intend investigating. disguise.


S - 62 1 X 3 220 rpm F/V1445 B - 309

B - 327


S - 73 1 X 4 150 rpm F/V S - 74 not on sector S - 75B **-** 306 B - 320

UNCLASS/MPM

B-103



SECRET



UK EYES 'B'

1540 · C/D PD C/S 5 - Identify S - 62

Nothing visual

Weather Wind Light Airs

Seastate 0

Cloud 100 %

Vis 4 NM

SSS 4

SVP 020 - 4882

080 - 4873

190 - 4874

250 - 4867

1547 B - 340 E - 79 DANGEROUS I BAND - Same bearing as S - 76

1600 B - 280 E - 82 I Band. Decca Navigation Radar

1615 Fishing Fleet now visual, closest one at 6000 yds
1 Factory/Refrigerator ship and 8 trawlers (Various designs)
No Warships

1616 COR 252 Received. Position signalled as ordered

CO COMMENT

- Sonar contact eventually classified visually as at least
 Warsaw Pact Deep Sea Trawlers. No Warships in amongst them.
 Detection range (back plotting) was 140 Kyds.
- 2. Sent my position in response to COR 252 since CTG 317.8 want water south of 50°S for attacks on ARGs. Sent a flash as I am well to the North.
- Intend going deep and fast ENE to my new patrol area.

1645 C/D 300 C/S 21 C/C 070

2000 Position 46 13.3S 58 59.1W

2038 Sunset

2130 C/D PD C/S 5 Routine, Fix, Domestics and ventilate

SSS 5

SVP 020 - 4867 100 - 4865

300 - 4862

Signals received COR 254, 255, 256


2230 C/D 320 C/S 21 C/C 105

2359 CO DAILY SUMMARY

- 1. A quiet day. Diverted at 1213 to NW after a ship contact (S-62) Classified as two Trawlers at 1400; but went on in to check no Warships in area and sighted at least 11 Warsaw Pact Stern Trawlers.
- 2. Received slightly corrupt signals sending me East to protect Amphibious Force. I believe that is the end of the action for us for a while.

SECULIAN ASSIMPM

UK EYES B'



3. Present problems - HF only partially readable and SSIXS has not been good for more than 18 hours - Have we a problem? Warner interference is intermittent.

TUESDAY 11 MAY 1982

0001 CO COMMENT

Fast passage to patrol in vicinity of 47S 54W

0257 C/D PD C/S 5 Routine, Fix and Domestics

0420 CO COMMENT

0905

Attempting to read Routines. HF trying, SSIXS reception non operational

0800 Position 46 48.3S 54 37.9W

C/D PD C/S 5 Routine. Fix and Ventilate

Weather: Wind 15 knots from 340 Vis 4 NM Seastate 3 from 340 SSS 3 - 4

Cloud 100 % SVP 020 - 4907

180 - 4907

240 - 4890

1000 CO COMMENT

What service! Requested via SSIXS for a rerun of COR 258 on HF and it came through 20 minutes later. Intend remaining at PD conducting a visual and ESM search until after the 1200 routine. Am in my new search area.

B - 278/166 T - 14 Diesel signature, spacing 2.6 Hz. Possibly the Fishing Fleet to the West. Very faint.

111 Sunrise

T - 14 faded


C/D 260 C/S 4


CO COMMENT

Intend to patrol within 30 NM of 47S 54W at 260 feet.


SECRET

THE EYES IN





UK EYES 'B'



C/D PD Routine and Fix. 1752

1815 CO COMMENT

> No new traffic for me. HF reception good, but SSIXS non operational.

CD 260 1922

Position: 46 30.4S 54 58.3W 2000

Weather Wind 20 knots from 230

Seastate 3 from 330 Cloud 20 %

Vis 5 NM

SSS 5

SVP 020 - 4925

210 - 4930

2017 Sunset

2359 CO DAILY SUMMARY

> Arrived in my new area (47S 54W) at 0900. Quiet day spent searching at slow speed. No contacts.

The problems with SSIXS are giving me cause for concern. At the moment I am receiving all my traffic HF.

WEDNESDAY 12 MAY 1982

C/D PD C/S 4 Routine, Fix and Domestics 0020

0025 Start ventilating

0038 Stopped ventilating - problem with upper supply fan

C/D 250 C/S 6 C/C 190 0105

CO COMMENT

Nine new signals, but only one for us - the rest are for VALIANT

and ONYX!


SSIXS reception non operational, HF good


As long as I get my signals somehow I shall not say anything

Intend continuing ASV patrol deep and repairing the upper supply fan

C/D PD C/S 5 Routine, Fix and Ventilate

Start Ventilating T - 15 Broadband signature 6.6 Hz spacing - Diesel to the South of us?







0800 Position: 47 32S 54 54W

Vis 4 NM

Weather Wind 20 knots from 290

SSS 6

Seastate 4 from 290

SVP 020 - 4908

Cloud 100%

150 - 4907

200 - 4895

0815

Stop ventilating

0907

C/D 260

CO COMMENT

Received COR 263 (Sitrep) 265 (Int) Still no reception on SSIXS - there is obviously a problem with the receiver. HF still good. Intend taking 1500 routine and transmitting Sitrep then.

1051 Sunrise

1140 T - 16 faded

T - 16 regained. Aft Beams 1255

CO COMMENT

T - 16 could be the Warsaw Pack Fishing Fleet to the West or British Merchant Vessels and RFA's to the South of me

1632 C/D PD C/S 5 Routine. Fix. Transmit Sitrep

1700 CO COMMENT

Received COR 266 which stated that ARG Surface Group may sortie East against FEARLESS Group. Intend heading to the NE corner of my area (120 NM NNE of me) to be close to intercepting them if required.


1900 B 295/065 T - 17 at 150 Hz with 2.6Hz spacing - probably diesel

1906 C/C 220 to resolve ambiguity on T-17

1915 B - 297 T - 17 Ambiguity resolved

CO COMMENT

Am still at PD trying to decrypt 3 groupers (COR 264, 267 and 268). COR 267 eventually broken - to reveal only two lines of text that were Top Secret. The rest could have been in plain language. is most frustrating. If I had been trying to make a fast SOA I would be pushed to keep up with it.





1926 C/C 000 to close T - 17

1955 C/D 260 C/S 8

2000 Position 47 31.85 54 16.4W

Weather Wind 15 knots from 270 Vis 5 NM Seastate 2 from 270 SSS 4 - 5

Cloud 100%

2015 Sunset

2359 CO DAILY SUMMARY

Another quiet day with no contacts. My concern over my communications equipment remains the same.

THURSDAY 13 MAY 1982

OOO1 C/D PD C/S 6 Routine, Fix and Ventilate T - 17 faded

0010 Start Ventilating

0025 T - 18 Low channel aft 11.6Hz spacing Diesel signature - very fuzzy

0110 Stop ventilating

0155 C/D 140 C/S 4

CO COMMENT

No reception SSIXS. Poor HF reception. Intend heading NNE at 140' keeping 2001 just above the layer. Will take the 0700 routine.

0702 C/D PD C/S 6 Routine, Domestics and Ventilate

<u>0725</u> T - 19 same classification as T - 18. We only seem to get this at PD - could be OSN.

0748 C/C 120 to resolve bearing ambiguity of T - 19

<u>0752</u> T - 19 faded

Traffic received COR 270, 272, 273


0800 Position 46 37.3S 53 50.5W

Weather Wind 10 knots from 300 Vis 3 NM Seastate 3 from 300 SSS 3 - 4


Cloud 100%

0925 C/D 140

SECRET B-112



. 1



1028 Sunrise

1502 C/D PD Routine, Fix

1650 CO COMMENT

Intend conducting a visual and ESM search until after the 1800 routine has been received

1828 C/D 200

Traffic received COR 274, 275, 276, 277, 278

CO COMMENT

Glad to see SPLENDID is on her way back.

1855 B - 270 S - 76. Audible whine at 694 Hz, very unstable C/C 270 to point and establish a bearing rate

1945 S76 FCS (Poor) 262/24 kyds 070/10 A0B 10 starboard

1947 C/D 100 to penetrate layer to check intensity of S76

1955 B - 270 S - 76 Occasional flutter audible, from gram 1 X 4 132 revs M/V.

CO COMMENT

I shall conduct a ranging manoeuvre. If S - 76 is at long range I shall sprint down the bearing to investigate

2000 Position 45 40.8S 53 47.4W C/S 12 C/C 180 Ranging Manoeuvre

2016 Sunset

2020 C/D 300 C/S 21 C/C 270


CO COMMENT

My ranging leg did not alter S-76 bearing rate so the contact is at long range. Will sprint for 40 minutes.

2022 B - 287 S - 78. In/Out, blade flutter and whine audible

CO COMMENT

This could be S - 76, if it is, the range is a lot less than I thought FCS (Poor) 287/12 kyds 050/12 AOB 55 starboard



2025 <u>CO COMMENT</u>

S - 78 has suddenly 'broken' right so is obviously very close. Will refine the FCS and then go to PD for a look C/D 200 C/S 8

2030 S - 78 FCS (Average) 330/6.2 kyds 052/10 A0B 97 starboard

2049 C/D PD C/S 6 C/C 000 - look at S - 78

2045 B - 092 S - 78. Large M/V. Brightly illuminated upper decks.

CO COMMENT

Am right astern of S - 78. Will go deep and run up on her port side, then return to PD to check her type. FCS (Good) 092/4 kyds 085/16 175 Port

2046 C/D 260 C/S 21 C/C 080

2115 C/D PD C/S 6 - identification

CO COMMENT

S - 78 Medium sized tanker. Dark funnel with red band at the top - probably Russian. From LOP her MLA 085 16 knots TPK 8.25 (1 X 4)

Initial contact range 44 kyds

Will conduct a Warner check on S - 78 when she has opened out to 8000 yds.

2140 B - 130 E - 81 I Band - DON 2. This is the same bearing as S - 78.

2359 CO DAILY SUMMARY

Another quiet day in my area, with the exception of S - 78 which provided a welcome change from "No contacts all sonar!"

FRIDAY 14 MAY 1982


0058 C/D PD Routine and fix.


CO COMMENT

COR 279 (ROE change) received 13 Mhz. It has taken me two hours to decode this grouper as HF reception is poor (13 MHz only frequency) and still no reception SSIXS.

Intend taking routines frequently today, because this is the last day the CVA can break East against the Amphibious groups; tomorrow is too late.

SECRET.





IIK EYES 'B'

C/D 260 0317

C/D PD Routine, fix and ventilate 0725

Start ventilating 0731

0800 Position 45 49S 53 30W

Weather Wind 25 knots from 280 Vis 10 NM Seastate 3 - 4 from 280 SSS 5

Cloud 40%

020 - 4922SVP 140 - 4922

200 - 4860

0837 Stop ventilating

Received COR 280 ARG Forces disposition

COR 281 Area/Sitrep

No new traffic 0903

C/D 260 0910

Sunrise 1045

1059 Port TG shut down for steam leak repair

B - 313 S - 20 Whine audible, possible ship contact 1120

1126 Port TG back on line

C/C 280 1936 range on S - 20 1151

CO COMMENT 1154

> Altering course across the bearing of S - 20 did not alter the bearing rate, so the range is very large

1158 C/D PD - Routine, Investigate bearing of S - 20 Nothing visual

1204 B - 325 S - 20 faded


C/D 260 1305


→ C/D PD - Routine and fix 1454


1815 CO COMMENT


> COR 283, a long grouper, is proving difficult to decode because of poor HF reception. Nothing on SSIXS. Will go deep while patching a copy - returning to PD at 2000 for the last two runs if required.











SECRET UNCLASS, MPM