### **RESTRICTED - SERVICE INQUIRY**

MAA DG/SI/01/11 SI ZG792

28 Jul 11

DG MAA

### SERVICE INQUIRY INVESTIGATING THE ACCIDENT TO TORNADO GR4 ZG792 ON 27 JAN 11

The Service Inquiry Panel assembled at RAF Wittering on 28 Jan 11 by order of DG MAA for the purpose of investigating the loss of Tornado GR4 ZG792, as detailed in the convening order MAA DG/SI/01/11 dated 28 Jan 11. The Panel has concluded its inquires and submits the provisional report (including the record of events and supporting paper work). The convening authority is invited to note that, to date, the Panel have been unable to positively determine the initial cause of the fault that led to

the accident.	
PRESIDENT	
Signed	
MEMBERS	
Signed	
Signed	
2. The following inquiry papers are enclosed:	
Part 1 (The Report)	
<ul> <li>1.1 This Covering Note and Panel Details</li> <li>1.2 Convening Orders and TORs</li> <li>1.3 Narrative of Events</li> <li>1.4 Findings</li> <li>1.5 Recommendations</li> <li>1.6 Convening Authority Comments</li> </ul>	
Part 2 (The Record of Proceedings)	
2.1 Diary of Events	

- 2.2 List of Witnesses
- 2.3 Witness Statements
- 2.4 List of Attendees
- 2.5 List of Exhibits
- 2.6 Exhibits
- 2.7 List of Annexes
- 2.8 Annexes
- 2.9 Schedule of Matters not Germane to the Inquiry
- 2.10 Master Schedule

### **RESTRICTED - SERVICE INQUIRY**

# MILITARY AVIATION AUTHORITY PROCEEDINGS OF A SERVICE INQUIRY INTO AN AIRCRAFT ACCIDENT

## **PART 1.1**

## **DETAILS OF THE PANEL**

Convened on 28 Jan 11 at Royal Air Force Wittering

By order of DG MAA

To inquire into an accident involving Tornado GR4 ZG792

## 1. Composition of the Panel

Duty	Rank, Name, Service No	Branch	Unit
President	Lt Cdr (S40)	X(P)	IV(R) Sqn
Members	Flt Lt (S40) (Replaced on Posting OOA)	GD(P)	II(AC) Sqn
	Flt Lt (S40)	Eng	TPF Marham
	Flt Lt (S40) (Replaced Flt Lt (S40)	GD(P)	XIII Sqn
In attendance	Sqn Ldr (S40)	Eng	MAAIB
	Ms (S40)	HF	RAFCAM
	Ms (S40)	HF	RAFCAM