UNCLASS/NPM

76



CONQUEROR

COERATION CORPORATE

UNCL**AS**S/NPM

PLAG OFFICER

PERCENTER

PERCENTE



PART TWO

OPERATION CORPORATE - ANNEX BRAVO

NARRATIVE

ONE COPY NO

THE FLAG OFFICER SUBMARINES TO:

List of Effective Pages:

Pages B - 1 to B - 222

(No Page B 134 and 169)

REFERENCE: HMS CONQUEROR'S No 226/1

OF 1 JULY 1982





OPERATION CORPORATE

S ZULU

M 6 APRIL 1982

Dived C220 S6 D PD

40.15.1N 07 12.9W Position Vis 2 miles

Wind 25 knots from 210 SSS 3 Weather

Sea state 4 from 210 SVF 000 4941 Cloud 100% 200 4942

CO COMMENT

The depth of water is now such that I can go faster dived. O/C 1200 Routine. Start Transit.

INTENTION

Fast passage SSW No stern arc policy. Aim to gain front of my MOVING HAVEN. Return to PD for O71200 WT ROUTINE and fix.

C/D 220 C/S 24 1315

1918 Sunset

2000 Position 46 36N 11 25W

SSS 3

SVP 000 4941 750 4945

CO DAJLY SUMMARY

Since diving have spent the time settling down to the fast transit and attempting to gain the front of the box.

WEDNESDAY 7 APRIL 1982

0632 Sunrise

42 20N 14 47W 0800 Position

SSS 3

SVP not taken

C/D PD C/S 4 - Routine, Fix, Domestics.

Weather: Wind 10 knots from 240

Vis 4 miles Sea State 3 from 240 SSS 2

Cloud 100 %

CO COMMENT

COR 007 update received. This signal instructs me that:-

Mk 24 may be losied into flooded tubes a.

Wk 8 may not yet be loaded b.

C/D 425 C/S 24 1448

Sunset 1945

Û

Position: 38 25N 17 25W 5000

SSS 2

SVP 060 4942

220 4944

300 4944

420 4947

2200 CO COMMENT

> WARNER confidence checks suggest the set is defective on the Fwd I Band crystal, which will require me to surface to repair.

2250 C/D PD to Tx Subnote change. No new traffic.

C/D 425 C/S 24 C/C 207 2320

CO DAILY SUMMARY

The day was spent transitting south at MAX REVS. On the watch Operational training progressing. Outstanding operational defects are a rattle forward above 9 knots and loss of Warner I band crystal. I intend to surface to fix both these when further south.

THURSDAY 8 APRIL 1982

0800 Position 34 22 N 19 57W

SSS 3

SVP not taken

0858 Sunrise

1439 C/D PD C/S 6 Routine. Fix. Domestics

Received COR OO8 - Sitrep, ROE and Areas

COR 009 - Subnote change

Weather Wind 3 knots from 250 Vis 10 miles SSS 2

Sea State Nil

Cloud 20% SVP See below

1545 C/D 750 for SVP 060 4980

570 4988

620 4980

730 4974

C/D 425 C/S 24 1602

1955 Sunset



2000 Fosition 30 27N 22 06W

SSS 2

SVP not taken

CO DAILY SUBMARY

The day has been spent again transitting south making good around 24 knots. COR 008 gives me a choice of clear ROE and an area to The aim is to work to the front of my box and to surface for defect repair.

FRIDAY 9 APRIL 1982

0752 Sunrise

0800 Position 26 58.9N 24 17.4W

SSS 2

SVP not taken

C/D PD C/S 6 Routine, Fix. Domestics 1729

C/D 425 C/S 24 1815

CO COMMENT

Part of SSIXS traffic received garbled. I will have to return to PD for reruns.

1840 C/D PD C/S 6 for SSIXS reruns

C/D 425 C/S 24 1847

CO COMMENT

All my traffic is in groups. If I cannot patch together a copy I shall have to return to PD for another rerun.

1920 C/D PD C/S 6 for SSIXS reruns

1935 C/D 425 C/S 24

2000 Sunset

> Position 22 11N 25 59W

Weather Wind 10 knots from 350

Seastate 2 from 350


S3S 2 Cloud 65% SVP

060 5010 300 5010

420 4993

Vis 4 miles

C/D PD C/S 6 for SSIXS remans 2310





2332 C/D 425 C/S 24

COW SUBLIARY

COR 011 not received COR 12,13,14 - INTSUM/ROE, details of General Mavigation received

CO DAILY SUBJARY

A full days transit without slowing gave me 567 miles run - not bad. From 1730 onwards I have been frequently returning to PD to read the SSIXS broadcast, since I need COR 10 - 14. I now intend to run until 0600 and try again. The **YIP** broadcast is not helping me.

SATUFDAY 10 APRIL 1982

O555 C/D PD C/S 6 - Routine, Fix, Domestics

Tx'd SSIXS (COP O11 not held)

Traffic received COR 015 - Areas

016 - ROE

017 - Inturdate

CO COMMENT

I am only 2 signals outstanding. COR 10 (VITAL for point TWO) and COR 011. I have asked for a rerun. I now have:-

- clear ROE for FI Area

- good Argentinian Int update

- Indication that 1 go to S Georgia area for surveillance Ops but no area.

With so much traffic coming in I believe I must read the broadcast twice a day.

0620 C/D 425 C/S 24

0736 Sunrise

0800 Position 17 56N 27 09W

SSS 2


SVP 060 5012

320 5016

340 5005

400 5000

1825 C/D PD C/S 6 - Routine. Fix, Domestics
No new traffic on SSIXS
BSAA ZBZ 2





1855 C/D 750 for SVP

Weather Wind 5 knots from 030

Seastate 2 from 000

Cloud 30 %

Vis 10 miles

SSS 2

SVP 060 5024

170 5024

210 5012

260 5012

320 4973

720 4942

1912 C/D 425 C/S 24

1946 Sunset

2000 Position 13 55N 27 14W

Weather Wind 10 kmots from 030 Vis 10 miles

Seastate 3 from 080 SSS 2

Cloud 30% SVP not taken

CO DAILY SUMMARY

Despite asking COR O11 has not been retransmitted. Otherwise no new traffic today. Electrolyser may be repaired at last.

SULDAY 11 APRIL 1982 - EASTER SUNDAY

0141 C/D 260 C/S 4 - Reactor Scram caused by spurious electrical fault

0749 Sunrise

0800 Position 09 22 N 27 32V

SSS 3

SVP 060 5038

160 5034

220 4975

300 4948


420 4935

0900 C/D PD C/S 6 C/C 200 - Routine. Fix. Domestics

CO COMEENT

Several signals required and SSIXS reception is not very good





1100

C/D PD C/S 6 C/C 180 for SSIXS reruns

Weather Wind 10 knots from 040

Vis 7 miles

Seastate 1 from 040

SSS 3

Cloud 100%

SVF as at 0800

COR 019 received - SITREP

115

C/D 425 C/S 6 C/C 183

OOW COMMENT

Having decoded COR 019 there is obviously more traffic waiting for me in the SSIXS Satellite

CO COMMENT

Have now received COR 18,19,20,21.

ROE have changed withdrawing right to attack. Our employment looks like support/SBS Ops in S Neorgia area. Believe there is more traffic in buffer - intend coming up again this afternoon.

1332

C/D PD C/S 6 for SSIXS

1344

C/D 425 C/S 24

OOW COMMENT

Despite sending a RASON we have received the same traffic as this morning. Must go to PD again to challenge SSIXS.

113

C/D PD C/S 6 for SSIXS.

433

C/D 425 C/S 24. All traffic received.

1855


Sunset


2000

Position 50 12.2N 27 46.4W SSS 3
SVP not taken

CO DAILY SUMMARY

Continued southerly transit. Although it is taking time I am still able to receive all my signal traffic. Very glad I was forewarned about SSIXS reception problems 20N - 20S before I sailed.





MOLDAY'12 AFRIL 1982

0650 Surfaced to remain MARNER and a casing rattle

0730 COR 022, 023 received

0749 Sunrise

0800 Position 0 44.7N 28 06.9W

> Vis 10 miles Weather Wind Light airs

> > Seastate 2 from 020 SSS surfaced SVP

Cloud 80%

0555 Dived SVP 060 5045

160 5045

230 5000

450 4932

730 4926

0930 CO COMMENT

> Surfaced at 0700 to repair the WARNER reception and a casing rattle. O/C bathy dip before proceeding. AIM NOW to get to the front of the box.

1009 Crossed the Equator.

Sunset

Position 03 37.4S 028 34.4W

SSS 2

SVP - not taken

CO DAILY SUMMARY

The rattle seems to have been cured - a loose plate was found. I have more confidence in the Warner set now. The day spent again making a fast transit.

TUESDAY 13 APRIL 1982

0759 Sunrise

0800 C/D PD C/S 6 for Routine, fix, domestics

08 21.7N 29 09.9W Position:

Wind 10 knots from 090 Weather: Vis 6 miles

> Seastate 2 from 100 SSS

Cloud SVP 030 5058 80%

220 5062 350 5030

2





C/D 425 C/S 24 0820

C/D PD C/S 6 for SSINS remins 0835

0843 C/D 425 C/S 24

CO COMMENT

Have received three groupers, but all corrupt. Intend going deep and fast whilst attempting to patch the signals. Will return for reruns after ratching.

0930 C/D PD C/S 6 for SSIXS reruns. COR 24,25,26 received

C/D 425 C/S 24 0940

Sunset 1954

Position: 12 49S 30 41W 2000

SSS 3

SVP not taken

C/D PD C/S 5 Routine. fix. domestics 2328

Wind light airs

Vis 8 miles

Seastate 1 no direction SSS 2

Cloud 10%

C/D 425 C/S 24

CO DAILY SUMMARY

Another day spent on fast passage

WEDNESDAY 14 APRIL 1982

COR 27 part 2, 28 received 0035 C/D 425 C/S 24

C/D PD C/S 6 Routine, Fix, Domestics 0548

Weather: Wind 5 kts from 100

Seastate 2 from 100

Cloud 30% SVP 060 5045

270 5048


420 5030

Received COR 027 Part 1

UNCLASS/NPM

Vis 10M

SSS 2



CO COMMENT

Having printed out COR 27 part 1 there is still traffic for me in the satellite. Intend returning to PD at 0900 to access the satellite and send a RASON.

0800 Position 17 06.1S 30 18.7W Weather, SVP as at 0548

0809 Sunrise

0900 C/D PD C/S 6 for BILAT/UK SSIXS COR 029,030,031 received

0930 CO COMMENT

There are a lot of signals for me today. BILAT SSIXS reception is much better than UK. Assuming a 5° bowdown angle is also improving reception once I have printed all in the Buffer. I shall RASON for those received and hopefully clear the satellite of all outstanding traffic.

1045 C/D PD C/S 6 for SSIXS

1130 C/D 425 C/S 24. All traffic received

1954 Sunset

2000 Position 21 22.5S 30 58.2W SSS 2 SVP not taken

CO DAILY SUMMARY

CO DAILI SCHMARI

3 useful signals this morning although with double encryption it needed more than one attempt to receive them. BILATEPAL SSIXS appears much better in this latitude. Excessive use of freshwater today has meant a return to PD at midnight. However the submarine is very hot.

THURSDAY 15 APRIL 1982

0013 C/D PD C/S 6 Routine, Fix and domestics

Weather Wind 5 knots from DDD Seastate 1 from DDD

Vis 4 miles SSS 1 - 2


Cloud 100%


0800 Position 25 52.3S 39 09.4W

SSS 2

SVP not taken

0824 Sunrise





C/D PD C/S 6 Routine, Fix, Domestics

Weather: Wind 5 knots from 025

Vis 10 miles

Seastate 1 from 025

SSS 1

Cloud 30%

Reactor Scram for controlling Rod Group Change

CO COMMENT

At FD for Routine, Domestics and Rod Group Change

C/D 750 for SVP 060 5029

160 5029

300 5008

560 4980

720 4970

255 C/D 425. Transmitting 2001 all modes

1330 B - 295 R - 39.5 KYDS S 33 Strong echo on IDD.

2 START EVENT 1501 - ACTIVE SOMAR CONTACT S 33

CO COMMENT

In position 27 24.6S 32 22.8W. S33 detected whilst transmitting on 2001 for test prior to entering the Exclusion Zone. Intention is to run for fifteen minutes and then transmit again to ascertain if S33 is a contact, a sea mount or a spurious echo.

5 transmissions. All scale 40 B - 263 R - 35 Kyds S33 FCS (poor) 267/38 Kyds 140/12 A0B 30 port C/S 20


C/S 4 C/C 230 to transmit

B - 281 R - 35 Kyds S - 33 FCS 281/35 kyds 010/7

CO COMMENT

Echo this time was very 'fuzzy'. Although IDD had 12 knots closing doppler, the LOP had S33 opening. There is no BC chart of this area, but I think this may be a pinnacle or the like. Intend running for anothe 20 minutes and then transmitting again to see if S33 is stationary. This contact is on the edge of my MXA.

C/S 24.



240

ू **१ २**२६

56



1420 C/S 4 to transmit

1428 B - 208 R - 39 kyds S34 - very 'fuzzy' echo. This is a bottom

B - 295 R - 27 kyds S33 zero doppler, stopped by LOP

1435 EID EVENT 1501

EVENT SUBMARY

S33 initially looked (IDD) and sounded (Sector) sufficiently like a submarine contact for further investigation. However second set of transmissions after 20 minutes and third set after a further 25 minutes were 'woolly' and unlike a submarine contact.

Command Final Classification - BOTTOM

1952 Sunset

2000 Fosition 29 31S 35 02W

SSS 2

SVP not taken

CO DAILY SUMMARY

Apart from the initial excitement of S33 another quiet day transitting south at full speed.


FRIDAY 16 APRIL 1982

<u>0800</u> Position: 34 23.5S 34 14.7W

SSS 2

SVP at 0850

0840 Sunrise



0850 C/D PD C/S 6 Routine, Fix, Domestics

Weather Wind 30 knots from 010 Seastate 3 - 4 from 000 Cloud 1005 Vis 4 miles SSS 2 - 3 SVP 060 4997 122 4997 222 4958 410 4953 425 4953

0919 CD 425 C/S 24

0920 CO COMMENT

I have received 3 groupers but no traffic list. I intend going deep and fast while I decode them and will then return to PD to RASON for them and receive any other traffic waiting for me

0935 CO COLDIENT

COR 039 changes my ROE so that I can attack any submarine detected in our Exclusion Zone to protect my integrity - assuming to be Argentinian.

1031 C/D PD C/S 6 for SSIXS

CO COMMENT

Operated the ALK buoy doors and fairlead to see if I could rid myself of a loud rattle - no success
Intend going deep and fast again to decode the traffic received, returning to PD later if required.

136 C/D PD C/S 6 for SSIXS
Barnstorms received 035, 036, 037, 038, 039

1150 C/D 425 C/S 24

1405 C/D PD C/S 6 - SSIXS and TRANSHIT SITREP 02
Barnstorms 041,042 received

CO COMMENT

I have been asked for and sent a ZID. However, I believe this to be unnecessary. As I understand it, when the SATELLITE is challenged and the signal number knocked off, then the SSIXS Broadcast Controller will know. Surely the American/British controllers talk to each other.



Op Order for Cheration FARAQUET - Royal Marine CGR 038 Officer is concerned about lack of frequencies or call signs. COR 040 outstanding

Sunset

2000

Position 38 23S 35 23W

SSS 3

SVP not taken

CO DAILY SUMMARY

Another day with a lot of traffic for us. I now have to read the Broadcast 1 in 4.

CATURDAY 17 AFRIL 1982

0248

C/D PD C/S 6 Routine, Fix, Domestics Traffic Received COR 040 (New SSIXS) COR 043 (TOP SECRET) COR 044 (ARG AUXS)

C/D 425 C/S 24

Position: 42 51.5S 36 41.8W

SSS 2

SVP as at 0925

0903

Sunrise

0925

C/D PD C/S 4 for SSIXS

Wind 20 kts from 185 Weather Seastate 3 from 185

Cloud 50%

Vis 6 miles

SSS 2

SVP 060 4948 160 4945

220 4910


300 4885

400 4880

C/D 425 C/S 24 C/C 189

OOW COMMENT

3 groupers received, but still 2 more in the satellite which must be COR 045 and 047.



C/D PD C/S 6 for SSIXS C/D 425 C/S 24 C/C 190

CO COMMENT

In the last 9 hours I have received COR 040, 044 to 047 and am close up with outstanding traffic.

COR 047 gives me two sets of ROE for "High Sea" Operation and within 200 NM of S GEORGIA/S SANDWICH ISLANDS. However, although they, together with Fatrol Instructions in COR 028, suggest I should attack Argentinian Ships, the tone of para 1 does not support

Intend asking for clarification on 2100 routine.

Sunset

Position 47 20.2S 37 45.9W SSS 2 SVP at at 2050

C/D PD C/S 6 for Routine, Fix, Domestics Weather: Wind 1C knots from 230 SEASTATE 3 from 230

Cloud 85%

Vis 4 miles SSS 2 SVP 020 - 4923

300 - 4926 420 - 4890 700 - 4868

Transmitted SITREP 03/82
Traffic received COR 048, 050. - 049 outstanding


C/D 425 C/S 24 ·


CO COMMENT

New ROE - Don't shoot as we await yet more diplomatic discussion.

CO DAILY SUMMARY

Two sets of ROE. I was not completely sure of my first orders and asked for clarification. Second one positive - Don't shoot. Several useful signals today, although their receipt slows me down. At present I have reduced speed to burn out poison in the plant. While in the Three quarter Fower State. Intention is to continue fast overnight.





SUNDAY 18 APRIL 1982

0007

C/S 20.

0630

CO COMMENT

Have entered Argentinian Declared 200 NM Exclusion Zone for South Georgia.

0700

C/D PD C/S 6 Routine, Fix, Domestics Received COR 049 (Rerun) and 052

0800

Position 50 52S 38 00W

Weather Wind 12 knots from 200 Seastate 3 from 200

Cloud 100%

Vis 6NM

SSS 1 - 2

SVP 020 - 4838 200 - 4838

260 **-** 4800 260 **-** 4800

530 - 4796

COMMENT

It would appear that there is still traffic for us in the satellite. Have also been asked for a rerun of Sitrep 3/82.

0926

Sunrise

10

C/D 750 for SVP

1132

C/D FD. Transmitted sonar - no icebergs or contacts Retransmitted Sitrep 3/82 and ZID Wind veering slightly now 15 kts from 235

Vis now only 4 NM in rain/mist

1146

B - 030 R - 8 kyds VO1 Possible ICEBERG - only brief glimpse Received COR 053. 054, 056. All traffic received.

CO COMMENT

Intend to remain at PD to close S Georgia

220

Vis 2 NM in fog

1350

Vis 1NM in fog. C/D 590 C/S 10

COMMENT

Have gone deep because of the fog and to monitor my array performance.

910 B - 185 Seismic Explosions S33. C/D 750 for SVP



C\D 500

5 transmissions sonar. B - 22 R 5 kyds S32. Very 'woolly' echo. Fossible iceberg.

933 C/D PD C/S 6 for SSIXS

1934 Sunset

1939 5 transmissions Sonar. No contacts.

2000 Position 52 38S 37 16W

Weather: Wind 25 kts from 260 Vis 4 NM

Seastate 7 from 270 SSS 3 Cloud 100% SVP 02

SVP 020 4795 300 4796 400 4775

700 4786

COR 059 received

2100 CO COMENT

Sent SITREP 4/82 - Weather and Bathy reports
Report of Seismic survey and intentions for

tomorrow

5 transmissions sonar B - 210 R - 37 Kyd S43. Very small echo. Stationary by LOP. Possible Iceberg.

COMMENT

Seismics continue to the SW. No obvious source.

CO DAILY SUMMARY

I am now in area, conducting ESM and Sonar Search as I approach S GEORGIA. Time/Distance problem prevented me making my "LANDFALL" in daylight today, so have adjusted my speed to achieve it tomorrow. Afternoon spent testing array which seems to be working well.


MONDAY 19 APRIL 1982


0001 CO COMMENT

Am transmitting sonar every 10 minutes looking for ice as the visibility is very poor.

- SECRET

UNCLASS/NPM





B - 247 S42. Irregular seismics occur in groups of 4 - 6 'Bangs' at a time.

COMMENT

These could be ice - noise at or near the North end of South Georgia. However they could possibly be machinery or explosions too. Will investigate further.

B - 183, S 56. Loud rearing noise

COMMENT

This loud roaring noise has been with us since $\underline{0300}$. It is coming from where FORTUNA Glacier meets the sea.

Position 53 52S 36 45W
Weather Wind 20 knots from 295 Vis 1.5NM (Mist)
Seastate 3 from 300 SSS 5
Cloud 100% SVP not taken

Started East/West Patrol 14 NM North of S Georgia

Sunrise Vis 1NM in fog and rain

CO COMMENT

Noise from starboard horn of WA4 is downgrading the set's performance. Am attempting a repair.

INTENTIONS

To make one sweep 4 NM off the coast listening on ESM and sonar in the hope that vis will improve. If no improvement when Cape George is abeam to starboard, I will set off to NW for an anti shipping patrol.


C/C 153 C/S 8

CO COMMENT

COR O64 received. This together with COR O61 (received last night) state main AIM is Anti Shipping Patrol Up threat. However I have time to conduct present sweep before setting off to NW for Anti Ship Patrol.

Fog has lifted at last. S Georgia visual at 5 NM.





1400 Weather now - Wind 40 knots from 260 Vis 10 NM Seastate 5 from 260 SSS 6 Cloud 60% SVF not taken

1425 C/C 225 C/S 6

1430 START EVENT 1901 - CLOSE PASS ON SOUTH GEORGIA ISLAND

7 photographs taken of Cumberland West Bay
RMO had a good look through the search periscope

1505 CO COMMENT

Have looked into Cumberland East and West Bays, Jason Harbour and Moraine Fjord. No sign of any ships or activity. Intention is to head NW to investigate Stromness Bay and Leith Harbour

1516 C/C 000 Appears to be a Northerly TS out of Cumberland Bay.

1530 C/C 294

1547 COMMENT

Am experiencing a pronounced anti - clockwise floodtide around Jason Island into Leith Harbour. Rate approximately $1\frac{1}{2}$ - 2 knots.

1550 C/C 280

1623 CO COMMENT


No sign of shipping or any activity in Stromness Bay or Leith Hárbour. Intend opening to NW to set up an Anti Shipping Patrol.


1624 C/C 333

1642 STOP EVENT 1901

END OF EVENT SUMMARY

The aim was initially to conduct sonar/ESM sweep along the coastline to check for contacts. When the visibility lifted I decided to close coast to check out the two inhabited areas for shipping or other activity. Secondary aim was to give 6 SBS the opportunity to see the coastline and to check out the Navigational aspects of a dived approach in case we have to land the SBS in the future.





No sign of activity. Soundings and navigational marks tied in. Tidal stream established.

I now intend to open from the coast. Set up an Anti Shipping Patrol, knowing there is "nothing over my shoulder"; catch up on the Broadcast Routines and repair a defect on the Search Feriscope.

1750 Tidal stream observed 6NM north of C Saunders; 000/1 knot.

800 The warner mast interference is much less now.

815 Received COR 067 telling me to leave Areas Dog 7 S - Z by 202200.

1928 Sunset

 2000
 Position 53 50S 36 59W
 Vis 10NM

 Weather Wind 15 knots from 285
 SSS 3 - 4

 Seastate 5 from 285
 SVP - not taken

 Cloud 10%

2211 Transmitted SITREP 05/82 COR 068 received

CO COMMENT

COR O68ROE change 3/82 gives me rules 4 and 5.

4 - MAY ATTACK ARG W/S, SM and AUX

5 - ANY NON NUC SM MAY BE PRESUMED ARG AND ATTACKED

Therefore am reloading 3 and 4 tubes with Mk 8 torpedoes to give me more flexibility


CO DAILY SUMMARY

While approaching S Georgia during forenoon, visibility lifted and gave me the opportunity for a visual sweep of Cumberland and Stromness Bays. Nothing was sighted. Afternoon was spent opening out towards my Anti Ship Patrol Area. New ROE allow me to shoot. Defects seem to be cleared, but the Search Periscope still worries me.


TUESDAY 20 APRIL 1982


B - 290 Seismics regained
COR 069 received giving TOT for MRR Victor. Intend being at PD to listen out for his broadcast.

0122 C/C 000 to try ranging manoeuvre on Seismics B 280 S26.



190000 - 200000 UNCLASS/NPM





S 26 B - 270 R - 11 Hyds 0135

Transmitted sonar - no echoes

C/C 310 0140

c/c 285 0205

C/D 590 C/S 21 to patrol area in DOG 6 0240

C/D 750 for SVP **U730**

Routine, Fix, Domestics and listen for ARR Aircraft C/D PD 0752

53 10S 41 02W 0800 Position.

Vis 2 NM Weather Wind 20 knots from 270

SSS 3 - 4 Seastate 3 from 270

SVP 020 - 4802 Cloud 100%

200 - 4804

360 - 4775

700 - 4785

CO COMMENT

At PD listening watch for the MRR A/C Search Periscope is again defective Weapon load now 2 X Mk 24 4 X Mk 8

0942 Sunrise

1000 CO COMMENT

> Nothing heard of Victor MRR - he would only transmit if he had something to say, but I would have expected to detect his radar transmissions


B - 185 E 58 PRT 1.3 PW 799 Sector scan 1.3/sec 1045 PW 200 Sector scan

Possible #25 from a Victor Nothing heard on any frequencies

1110 AJE on top of WT mast seen to be damaged, and part of the mast fairing is missing.

CO COMMENT

AJE has been damaged. Implications are that if it goes we lose SSIXS and therefore comms with CTG. HF is bad. Intentions are to surface tonight to repair (Night better since it denies MPA visual search). Until then intend remaining at PD at less than 7 knots with mast slightly raised.



CUR 0/3 received - Area Allocation. To be out of ν 0G 7 by 210000

CO COLLENT

I have already moved to the West.

Two Defects - the first was a SMAFU alarm on 6 tube that proved to be a flooded 'C' unit. Now cleared. The second was the torque-assist on the search periscope - that, too, is now correct.

TO5 Diesel Signature in low band at 6.5 Hz spacing.

B - 297 SO3 LF meter swing on sector. Could tie in with TO5.

C/C 270 C/S 6 to resolve ambiguity on TO5.

S03 faded

TO5. Very intermittent contact in after beams - is to the East of me.

TO5 faded

Sunset

Position 52 42S 42 22W

Weather Wind 15 knots from 270

Seastate 3 - 4 from 270

Cloud 100%

Vis 4 MA

SSS 3 - 4

SVP not taken

Surfaced for AJE repair

CO COMMENT

Surfaced in position 52 43S 42 3OW to repair damaged AJE aerial. It is too rough for a check of the casing for rattles.

Flash COR 079 received. Operation DANDELION initiated - The retaking of S Georgia. My instructions are to prevent Argentinian Ships joining in.

CO DAILY SUMMARY

1. The day has been spent making ground to the NW and patrolling a box to the NW of SHAG ROCKS. Weapon load is now a mix of Nk 8 and Nk 24 which gives me flexibility.





CO DAILY SUMMARY Contd

The day has also been regued with defects. The major one to the ALM/AJE aerials is much greater than first anticipated and repair still continues. Others have been:-

More warner interference Loss of Torque assist to the Search Feriscope External Hydraulic oil contamination SNAFU alarm to No 6 Tube

- 2. Nothing was heard of the MRR aircraft, but I doubt if he had anything to report.
- Fresent ROE and receipt of Initiation of Operation DANDELION means I am now (once I have dived!) in an aggressive Anti Ship posture.

WEDNESDAY 21 APRIL 1982

0147 C/C as required to improve working conditions on the bridge.

CO COMMENT

Cutting out the WT Mast shutter is taking much longer than expected, as the gusting winds and rain keep putting the torch flame out.

0800

Position

53 30S 42 14W

Weather

Wind 25 knots from 280

Vis 4NM

Seastate 4 from 280 Cloud 64%

SSS)
SVP Surfaced

0850

CO COMMENT

At last - the shutter has been cut out. I should be ready to dive by 0930 all being well.


0942


Sunrise


1005

CO COMMENT

Replacing the AJE is taking longer than expected. However it is almost ready so I shall finish the job. Although it is after sunrise and I feel a little maked on the surface, there are a lot of snow storms which make visual detection a very small possibility.







No success on SSIXS transmission. Investigating the AJE mast further. The AJE will now clear the fin, provided the mast doesn't bend anymore.

1215 CO COMMENT

Sitrep 6/82 transmitted successfully. In addition to the AJE defect, a plug at the base of the mast was damaged. Nothing is ever straightforward.

- 1315 Dived.
- 1420 Have retransmitted Sitrep 6/82 as a rerun was requested.
- 1440 C/D 260 C/C 250 C/S 15
- 1510 C/C 300
- 1512 B 014 S04 Possible submarine contact.
- 1514 START EVENT 2101 POSSIBLE SUBMARINE CONTACT SO4
- 1519 C/C 335
- 1521 Transmitted sonar broadcast 100/20 scale 20
 B 042 R 4 kyds
 This is a good strong echo probably bottom, however, there is nothing aural, nothing on the array, on 185, LF and no biological.
- 1522 SO4 FCS (poor) 045/4 kyds 080/4 AOB 145 starboard


CO COMENT

This contact is certainly not a surface one, and could well be a dived conventional submarine on main motors. If I can identify it as such I will attack (SAN LUIS is unlocated). Bow Caps open.

- 1526 C/D 425 C/C 095 to look below the thermocline.
- 5 transmissions. B 083 possible contact looks like bottom.
- 534 C/S 14

CO COMMENT

Will sprint for 6 minutes, slow down and come shallow to listen





1539 B - U74 2 pens HF, possible SC4 regained.

542 5 transmissions sonar

546 B - 020 R 4.7 kyds. Contact looks like the sea bed.

1547 C/C 350 C/D 180 504 FCS(Poor) 020/4.7 Eyds 066/9 between datums on LOP.

5 transmissions sonar. No contacts.

555 C/C 245 C/S 15 C/D 425 Clearing datum

600 END EVENT 2101

END OF EVENT SUMMARY

Initial contact of 2 pens HF had the indications of being a possible submarine centact with a CPA at 1510 of about 2.8 kyds. Further tracking and going active failed to produce a likely solution or confirmation. No IN/OUT or BIO.

Command Classification: BIC

949 Sunset

958 C/D PD for SSIXS

Meather Wind 40 knots from 250 Vis 4 NM Seastate 6 from 250 SSS 6

Cloud 75% SVP 020 - 4805 260 - 4805

Received COR 082, 084, 085, 087 - more to come

CO COMMENT

The weather is Rough! I can see little point in conducting my search at PD. Therefore have gone deep.

COR 087 - New ROE 5 - Attack ARG Submarines outside of 200 NM of S Georgia

C/D PD C/S 6 C/C 160 - Routine, Fix, Domestics Received COR 083, 088.



CO COMMENT

Now close up on traffic. Intend moving to the SW of SHAG ROCK to intercept the Merchant Ship. SSLS is greater than 15 knots. No fix taken at FD so running the BU to tell me when I cross the 100 fathom line

Sudden shelving to a minimum sounding below the keel of 17 fathoms.

C/D 200 C/S 8 C/C 000

Fosition 53 12.5S 42 33.4W


2330 CO COMMENT

While travelling at 15 knots to a position to the west of SHAG ROCKS the sounding rapidly shelved to 60 fathoms where the charted depth was greater than 130 fathoms. The soundings are sparse but there is a ridge to the west of SHAG ROCK. I have returned to the North and chickened out. Intend running to the East to take up patrol to the east of SHAG ROCKS.

CO DAILY SUMMARY

- 1. After 19 hours unpleasant work, the mast problem was eventually sorted out. The receipt of COR 073 SSIXS downtime helped tie up a few thoughts.
- 2. The Anti-ship patrol produced an interesting contact 1510 to 1600. 2 pens HF and no surface or BIO characteristics. Could have been a submarine (SAN LUIS is unaccounted for) but I believe unlikely because of:
 - a. Speed around 10 knots
 - b. Leck of other noise
 - c. No active contact
- 3. While attempting to get SW of SHAG ROCK the uncharted shoal disturbed me and I chickened out since I would anyway have spent the night'falling back' to the east.
- 4. The weather is very rough which must slow my target down. Today has produced less sefects, but the other Mk 24 (5 tube) had a flooded C Unit possibly condensation.







THURSDAY 22 APRIL 1982

0110 C/D 425 C/S 21 C/C 110

0518 C/S 6 CSA

0540 C/D PD Routine, Fix

0600 Weather Wind 30 knots from 280 Vis 4 NM

Seastate 5 from 280 SSS 4

Cloud 70% SVP 020 - 4797 260 - 4802

Transmitted SITREP 07/82
Traffic Received COR 089. 090

0625 C/D 260 C/S 15

0705 C/S 6 Start tonal search

0800 Fosition 53 47S 39 54W

9943 Sunrise

1043 C/D PD C/S 6

00 Weather now Wind 15 knots from 323 Vis 4 NM

Seastate 3 - 4 from 323 SSS 3 - 4

Cloud 100% SVP 020 - 4805 260 - 4805

CO COMMENT

Weather is much calmer than last night.

Intend patrolling at PD within 10 NE of 53~50~S 40W keeping BB and NB Sonar Arcs open to the west to cover the widest range of Approach options.

I have been patrolling LONG 40 since 220500 which is 30 mins ahead of Targets DR if he had managed to maintain 14 knots. This I believe to be unlikely in the weather conditions of the last 24 hours. His likely approach course to S Georgia is covered by a patrol line of 100 NH at 40 W, although his most probable is covered by a 50 NH patrol line.

\$1250 C/D 300

CONSIENT

Going deep so that the Doctor can remove a metal splinter from an eye while the boat is still .

300 C/D 75U for SVP





1345 · C/D PD C/S 5 C/C 230

SVP 020 - 4801

202 - 4803

300 - 4777

505 - 4773

610 - 4792

750 - 4790

412 Received COR 093 (- 3 and 4 tubes preferred Mak 24)

CO COMMENT

I wonder whether the FOSM staff Officer would like to participate in our RM equipment/Torpedo juagle to achieve this?!

610 C/C 045. Reversing the patrol line

800 COR 094, 095 received

842 TO1 - possible diesel signature at 70 Hz. 11.6 Hz spacing.

Very fuzzy and intermittent

1852 TO1 faded

933 Sunset

951 T01 resained, still very faint and fuzzy

1953 TO1 faded

00 Position 53 47S 40 07W

Weather 25 knots from 310 Vis 2.5 NM

Seastate 5 from 280 SSS 3 - 4

Cloud 100% SVP - not taken

2100 Close up in traffic

C/D 425. Starting torpedo shuffle to put Mk 24's up 3 and 4 tubes.

CO DAILY SUMMARY

Uneventful day spent patrolling within 10 NM of 53 50W. COR 094 invites me to be in patrol area 46S, 48S to 50W. 50 30W at 241200 for next phase of Operation to cover Argentinian force if it tries to oppose TG 317.8

630 MM in 36 hours = 17.5 knots, therefore on my way.



2200002 - 2300002

aspo 230000) +1200 22004 40°W

0 19.9

INCH= 199 mLs.

UNCLASS/NPM

7 23 APRIL 1982

c/s 20

C/D PD C/S 6 Routine and fix

COR 096, 097 received C/D 425 C/S 21

CO COMMENT

Have left S Georgia Argentinian MEZ. My ROE now changed. Only Argentinian submarines may be attacked. In theory, I should withdraw my Mk 8 torpedoes - in practice, I won't.

Position: 51°33'S 42°40'W

Weather: Wind 15 knots from 290 Vis: 5 NM

Sea State: 4 from 290 SSS: 3-4

Cloud: 30% SVP: 060 - 4822

260 **-** 4825 305 **-** 4816

310 - 4790

410 - 4788

C/D PD C/S 6 for SSIXS re-run (COR 096, 097 were received corrupt).

C/D 425 C/S 21

Sunrise

c/c 303

CO COMMENT

Torpedo re-load completed. Now have: 1,2,5,6 - Mk 8 3,4 - Mk 24

Achieving a sensible stowage of re-loads will take considerably longer.

C/D PD C/S 6 C/C 000 Routine, fix and domestics.

T-02 - strong doublet at 50 Hz in forward beams - possible diesel signature.

T-02 faded


C/D 425 C/S 21


COR 098 received (Areas for Pt One, Pt Two)

Position: 49°02'S 46°58'W SSS: 3 SVP: Not taken

Sunset







2359 CO DAILY SUMMARY

Day spent transitting NV out of the MEZ around S GEORGIA, towards my new area for the R/V with the Battle Group.

SATURDAY 24 APRIL 1982

6037 C/D PD C/S 6 C/C 300 Routine, Fix, Domestics, Transmit Sitrep

0130 CO COMMENT

Received COR 099 showing that a Submarine threat now exists at S Georgia and ordering us to counter it. Ordered to patrol in the Area where we were 27 hours ago.

0145 C/C 120

O240 CO COMMENT

SSIXS reception is very poor. - VK worse than BILAT, so I need a number of copies of each signal to patch together a fair copy. This has lost me $1\frac{1}{2}$ hours. On my way at 21 knots.

Signals received COR 099 - OF FARAQUET

100 - TOP SECRET

101 - SITREP

102 - TOP SECRET

103 - AREAS

SVP 020 - 4916

200 - 4917

300 - 4920

410 - 4901

0800 Fosition 49 27S 46 57W

Weather) Not Taken


0920 T - 03 held 58.7 Hz


0925 ° ∽ C/D 260 T - 03 faded

0935 C/D 425 T - 03 not regained

0953 C/D PD for SSIXS

0958 Sunrise





UNGL**AS**S/NPM

Weather Wind 10 knots from 310 Seastate 2 from 310

Cloud 100 %

Vis 2 NE SSS 2

SSS 2

SVP 200 - 4852

310 - 4843

315 - 4835

332 - 4830

425 - 4830

C/D 425 C/S 20

CO COMMENT

I think this tonal is VS: Yet another $1\frac{1}{2}$ hours wasted.

CO COMMENT

COR 099 tasked me to conduct covert ASW patrol in vicinity 53S 40W. However COR 102 (7 hours later) suggests the action is or will be to the North of Cumberland Bay - some 130 NM further East. My intention is to proceed fast to 53S 38 30W (ETA around 250800) and search ESE from there. No doubt SS SANTA FE snorts at night in shallow water so I will not be able to intercept until night 25/26. Intend taking 1800 routine and will respond to further information.

C/D PD C/S 6 for R outine, Fix, Domestics Weather Wind 10 knots from 315

Seastate 2 from 315 Cloud 100% Vis 0.5 NM (FOG)

SSS 3 - 4

SVP 020 - 4820

290 - 4823

310 - 4794

410 - 4790

CO COMMENT

COR 106 received ASW operations with ENDURANCE (WASP fitted with AS 12 missile) to North of S Georgia 23/4 Position for SANTA FE 49 54S 38 45W is some 300 NM from CRYTVIKEN. Therefore, either the position is wrong (PLYMOUTH ESM would support that) or ETA will be much later; 48 hours from 23 April = 25 April (although ETA is 241100). Therefore confusing. However the day of 25 or the night 25/26 are when we might get our first sniff of him. Intentions remain the same.

Sunset

Position 51 328 42 19W

Weather) at 1750

C/D 300

CO COMMENT

Am changing my tubes state to - 1,2,6 - Mk 8

3,4,5 - 胚 24

in view of my tasking against SS SANTE FE

CO DAILY STEMARY

Have spent the day heading SE back to S Georgia after receiving COP OOD re tasking me against SS SAEMA DO

