


Assembly axis shown as the dash-dot centerline; components separate along it.