

1 ID Tracing (tabular)

Overview

Menu	Quality management → Process analysis → ID tracing
Transaction code	cidt
Function authorization	cidt

This document describes the application "ID Tracing (tabular)" in the Manufacturing Operation Center (MOC).

Usage

ID Tracing enables the tabular presentation and analysis of process values that can be selected referring to search keys (IDs). Search keys are identification tags provided by the machine. They are used to identify measurement tuples instead of or in addition to the machine and time stamps of data collected in the database.

Integration

Measured values must be collected and saved based on IDs in order to use this function. For this purpose, at least one channel with the data type "tag" must be defined in the application "PDV - logical channels" and data collection must be configured accordingly.

Selection parameters

IDs can be selected in the selection panel. The following selection criteria are available in the application:

Tag type:

Identifies the key field. The name of the ID tag.

Tag ID

Search value of the selected ID tag.

Workplace

Number of the workplace as an additional search field. Is required, if the same tags are available at different machines/workplaces.

Time range from - to:

The data selected by the tag value is restricted temporally.

Consider the last time range of the tag value only

If this function is enabled the data selected is restricted to last time range recorded for the selected tag value.

Field descriptions

This tabular report shows the process characteristics recorded and saved in the database including the following information:

Characteristic

Technical name of the characteristic or the entered process parameter

Designation

Defined characteristic name

Machine

Defined machine

Process parameters

Defined process parameter

Target value

The target value defined for this recorded process parameter at that specific point in time

UTL

The upper tolerance limit defined for this recorded process parameter at that specific point in time

UPAL

The upper process action limit defined for this recorded process parameter at that specific point in time

LTL

The lower tolerance limit defined for this recorded process parameter at that specific point in time

LPAL

The lower process action limit defined for this recorded process parameter at that specific point in time

Unit

Unit of the recorded characteristic

Measured value

Measured value recorded for the characteristic at the time of measurement

Time of measurement

Time of measurement of the characteristic

