

# 1 Resource Measures

## Summary

|                        |                                             |
|------------------------|---------------------------------------------|
| Menu                   | Master data → Resources → Resource measures |
| Transaction code       | resmea                                      |
| Function authorization | mdrmea.*                                    |


This document describes the application "Resource measures" within the Manufacturing Operation Center (MOC).

## Usage

Resources in terms of production resources and tools, (tools, devices, machine parts and peripheral devices) are often subject to small modifications, repairs, corrections or unplanned cleaning. However, these small activities performed on the resources often represent important factors for the service life and quality of the resources. Measures are taken to document these small activities without expending a great deal of effort.

Measures are created in a catalog as master data so that the documentation of the activities done can be checked. One measure is assigned to one resource family, respectively. In this way, a specific measures catalog is created for each type of resource, which can be used to document the activity done on the resource.

| Tool 1010-101/101 |              |                    |
|-------------------|--------------|--------------------|
| Date              | Measure      | Person responsible |
| 01.06.2010        | Cleaning     | Heiner Brandt      |
| 28.07.2010        | Repair       | Mathias Schmidt    |
| 05.09.2010        | Quality test | Raimund Müller     |
| 07.09.2010        | Correction   | Mathias Schmidt    |
| 30.09.2010        | Inspection   | Albert Blond       |



The measures defined in this catalog serve as text templates for entering measures in the resource overview or the resource information. If the measure is entered or selected there, the measure is accepted with measure designation and comment in the message dialog. The measure comment can be overwritten.

## Selection criteria

In the selection panel, filters can be used for both superior and assigned resources. The following selection criteria are available in the respective application:

### Resource family

Family to which the resource is assigned.

### Measure

Number of the measure.

### Designation

Designation of the measure.

### Show comments

Check box for displaying the comments in another row in the table.

## Field descriptions

### Resource family

Resource families for which the measure has been defined.

### Measure

Number of the measure. The measure number must be unique for a resource family.

### Designation

Designation of the measure. Short text of the measure.

**Description**

Long text for describing the measure.

**Responsibility area**

Responsibility area of the measure. The responsibility area can be used to control which users can see, create, modify and/or delete the measures.

**Editor**

Name of the user that most recently modified the measure.

**Date**

Date on which the measure was created or most recently modified.

**Time**

Time at which the measure was created or most recently modified.

**Comment**

Free text for the measure. Due to the comment's length, it is displayed in another row of the table.