

# 1 Configuration of Minimum Storage Times and Expiry Durations

## Usage

You use minimum storage time to ensure processing-related waiting times within production and to prevent input materials with a minimum storage time that has not expired from being logged on.

You use warning time to be notified in advance in the evaluations [warning report](#) and [expiry preview](#) that material is due to expire.

You use expiry limit to define the maximum storage life of a material.

## Requirements

You defined material types for the materials you use.

## Procedure

Define on which level the times should be maintained.

- You can update the settings on the material type level in the [material type configuration](#).
- When assigning [material to material type](#), you can overwrite the material type settings for selected materials.

Update the times on the level you have selected.

## Results

The times are defined.