

1 Monitoring Availability Dates

Requirement

You defined the process time defaults for minimum storage time, warning time and/or expiry time in [Material type](#) or in [Assignment of material to material type](#).

You scheduled the [job](#) in the scheduler.

Procedure the system follows during cyclic monitoring

Batches, which because of the *minimum storage time* configuration, were set to status "M" (minimum storage time) at the time the batch was created are set to status "F" (free) once the minimum storage time has expired.

A batch is considered expired if the period of time between when the batch was created and the current time is greater than the period of time defined in the *Expiry limit* configuration. If this is the case, the batch is set to status "V" (expired).

The status modification as a result of the processing step is logged and is shown in the [batch history](#).

Procedure the system follows during input batch logon

When a batch is logged on as an input batch, a plausibility check is run to verify the minimum storage time and the expiry time.