

1 Server-Controlled Shift Change

Purpose

The server-controlled shift change allows you to differentiate between MDE and BDE data regarding shifts.

Integration

The origin of data does not affect the server-controlled shift change.

Requirements

One of the following requirements must be met in order for the server-controlled shift change to take place for a machine/workplace:

- The machine is not [assigned to a terminal](#).
- The machine is assigned to a terminal. But this terminal is not assigned the option "Operated as HYDRA-MDE terminal" in the [Terminal configuration](#) (go to *Terminal configuration --> General --> Configuration*).
- The machine is assigned to a terminal. This terminal is assigned the option "Operated as HYDRA-MDE terminal". But in the machine/terminal assignment, this machine is configured with "BDE processing".

This [document](#) provides detailed information on how to configure and activate the server-controlled shift change.

Procedure of server-controlled shift change

Prior to posting data, the central posting process (hymw.exe/out) checks for BDE machines if the server-controlled shift change is:

- enabled for specific machines or
- for the entire system.

If the server-controlled shift change is enabled for the machine (either option), the system checks if the shift has changed since the last posting of this machine. If so, the system triggers an M_ASW dialog (shift change dialog) for the affected machine.

Cyclic trigger

Use a cyclic program (ade_aswtrigger.exe/out) to verify if a shift change should be carried out for BDE machines. An automatic status update (M_AST) is triggered if a shift change is required. This status update then initiates the server-controlled shift change.

Integration: automatic logon of continuous monitoring orders

The procedure is as follows if the shift change coincides with the start time of a [continuous monitoring order](#):

1. Log off a running operation at the time the shift changes (exact time stamp).
2. Change shifts at the time of the shift change (exact time stamp).
3. Log on the new operation at the time the shift changes (exact time stamp).