

1 ATP Inspection Groups

Overview

Menu	Master data -> production control -> ATP inspection groups
Transaction code	atpig
Function authorization	atpig

This document describes the application "ATP inspection groups" in the MES Operation Center (MOC).

Purpose

You use this function to create and modify ATP inspection groups in the system.

Integration

ATP inspection groups are used in the system to visualize material processing in the HYDRA Shop Floor Scheduling module.

Selection criteria

The application provides the following selection criteria:

Name

Selection using the name of the ATP inspection group

Field descriptions

Name

Name of the ATP inspection group

Active

Shows which application can display the ATP inspection group.

Consumption during setup time

This field shows if materials assigned to this ATP inspection group are consumed during setup.

Consumption during processing time

This field shows if materials assigned to this ATP inspection group are consumed during processing.



Please note that when creating and changing ATP inspection groups at least one option "Consumption during setup time" or "Consumption during processing time" is active. Otherwise,

you cannot create or change a data record.

Consumption type


- **Complete:** Material is completely consumed at the beginning of the OP (operation).
- **Linear:** Material is continuously consumed during the OP.
- **Discrete:** Material is evenly consumed during the OP in specified numbers.

"Fragmented size" (piece-sized)

Shows material quantities consumed during *discrete* consumption. Example: "Fragmented size" of 50 means that the consumption is divided into steps of 50 over the total operation.

Example:

OP 0100 (processing time 1 hour) requires 200 pieces of an article (400 available at start). If the machine uses a piece size of "50", material consumption is as follows: The required material of 200 pieces would be divided into four blocks of 50 and evenly consumed during the processing time. At the end of the OP 200 pieces of the required article (material) are available.



Discard parts

Gives the number of left over material to be cleared at the end of an operation. If that option is active, then consumption at the end of an operation is rounded up.

Provision during processing time

This field shows the availability of the produced material during processing time.

Provision during teardown time

This field shows the availability of the produced material during teardown/retooling time.

Provision during wait time

This field shows the availability of the produced material during wait time.



Please note that when creating and changing ATP inspection groups at least one option "Provision during processing time", "Provision during teardown time" or "Provision during wait time" is active. Otherwise, you cannot create or change a data record.

Type of provision


- **Complete:** All the material is provided at the end of the operation.
- **Linear:** Material is made available evenly during operation.
- **Discrete:** Material is made available evenly distributed during the OP in specified numbers.

"Fragmented size" (piece-sized)

Shows material quantities provided with type *discrete*. Example: "Fragmented size" of 50 means that the provision is divided into steps of 50 for the total operation.

Example:

OP 0200 (processing time 1 hour) produces a total of 200 pieces of an article (150 available at start). If the machine uses a piece size of "50", material production is as follows: The produced material of 200 pieces would be divided into four blocks of 50 and evenly produced during the processing time. At the end of the OP 350 pieces of the required article (material) are available.



Modified by

Last editor of the ATP inspection group.

Modified on

Point in time of last change of this ATP inspection group.

"General" tab

**Add**

Opens the dialog to add an ATP inspection group.

**Copy**

Opens the dialog to copy an ATP inspection group.

**Edit**

Opens the dialog to edit an ATP inspection group.

**Delete**

Deletes an ATP inspection group.