

1 qs-STAT® Data Export


Summary

This document describes the application "qs-STAT® data export" within the Manufacturing Operation Center (MOC).

Starting the Function

Menu	Quality management --> QM evaluation --> qs-STAT® data export
Transaction code	qsstat
Function authorization	qsstat.export

Default Application Layout



Utilization

This application allows for characteristics (sample data) to be transferred to the program package qs-STAT® for further analysis. The amount of data selected can be restricted by a variety of filters based on orders, available inspection plans, characteristics and samples.

Selection criteria

At least the fields

- Area type
- Area

have to be filled out to be able request data. An error message occurs if data is requested and these two filter criteria are not filled out.

If the checkbox "summarize characteristics" is checked, all inspection results matching the filter criteria are exported as "one characteristic" to qs-STAT®. This is also the case if HYDRA inspection results are recorded based on several different characteristics.

The other filter criteria are not explained in detail here, as they are self-explanatory.

Selection of the data set

In this application characteristics can generally be identified either by the OP sequence number or the characteristic number.

If filtered by the OP sequence, a characteristic can be identified uniquely within an inspection plan. This can be useful, for example, even if an inspection plan includes several characteristics with identical characteristic number.

If filtered by the characteristic number, reports can also be started if the number and/or order of characteristics has changed over several inspection plans.

Automatic start of qs-STAT®

The user has to make sure that the file extension is connected with the correct program to start the relevant qs-STAT® program automatically after an export. If assistance is required Q-DAS (manufacturer of qs-STAT®) has to be contacted.