

1 Scrap Statistics

Overview

Menu	Order management → Order controlling → Scrap statistics
Transaction code	scrst
Function authorization	scrst

Any person in a company who wants to reduce scrap must have knowledge of how and where scrap is accrued. The *Scrap statistics* provide an overview of all scrap reasons and scrap quantities that were recorded in a specified period of time. The report also includes the scrap that has been recorded automatically. The *Scrap statistics* use graphic displays to show ranking lists of the most frequent scrap reasons.

Integration

The order-related log records of record type "T" are the data basis used to display quantities in the scrap statistics. The log records are generated on the shop floor terminal when part quantities are manually uploaded or when an operation is interrupted or logged off and quantities are recorded.

Selection criteria

The application provides the following selection criteria:

Workplace/short name/group/cost center/company/responsibility area

These fields specify the workplaces/machines that are used for the evaluation. To select an entry, you access the master data of the workplace/machine configuration.

Article/article designation

Selection by article or article designation

Order/order type

You can limit the evaluation to one order or order type.

Date

Enter a period of time to narrow down the log records displayed. The application selects the log records of record type "T" with a posting time that is included in the period of time specified.

Shift

In the period of time specified above, only those log records are selected that are assigned to the shift specified.

Time

In the period of time specified above, only those log records are selected that were booked in the time specified.

Reason

Selection based on a specific scrap reason.

Sales order

If a sales order is assigned to the production order, this sales order can be used to select the data.

Project number

If a project number is assigned to the production order, this number can be used to select the data.

Report group

Use the option *Report group* to narrow down the selection to a specific group of workplaces/machines. You must define the report group in the [group configuration](#).

Show yield

If this option is enabled, the yield recorded in the specified period of time is also displayed for the selected operation. Additional entries are added to the table. Note: the column *Yield* is not displayed by default. Use the column configurator to show the column.

Check responsibility area

Using this option, the user can specify if the system checks the responsibility area of the workplace or the responsibility area of the object operation/order to display data. To use this selection option, you require the following function authorizations: scrstPerf + chkresp.



This selection option is only available, if you enable the extension [scrst82](#).

Detail application *Scrap statistics*

The detail application *Scrap statistics* provides an overview of all scrap reasons and scrap quantities that were recorded in a specified period of time. The data selected is based on the order-related log records of record type "T". The quantities identified are always displayed in the primary quantity unit. To total the quantities, the system does not convert any quantity units.



The *Scrap statistics* only show operations that had at least one upload of a part quantity including scrap in the specified evaluation period.

Note: the column *Yield (P)* only displays yield quantities, if the option *Show yield* is enabled. Yield is shown in a separate row for each order/OP and workplace.

Notes on specific columns:

Scrap

The column *Scrap* shows the scrap quantity with reference to the scrap reason, the workplace and the order/operation.

Note: the scrap quantity shown can also be a negative quantity in certain cases. For example, this can be the case if scrap is offset against yield.

Scrap rate

Share of scrap (primary quantity unit) in the total quantity produced (primary quantity unit) of the operation in the evaluation period.

The total quantity is equal to the total of all four quantity accounts (yield, scrap, rework, open quantity). Note: rework quantity and open quantity are not shown in the *Scrap statistics*.

Calculation:

$$\text{Scrap rate} = 100.0 * \text{EGR_AUS} / (\text{ANR_GUTP} + \text{ANR_AUSP} + \text{ANR_NCHP} + \text{ANR_PRBP})$$

Detail application *Comparison: yield - scrap*

This detail application provides a comparison of the yield and scrap quantity (both in primary quantity unit). The comparison is shown in a bar chart. The bars show the ratio of the two quantity types. The percentage is visualized for each bar.



Note: the yield displayed is calculated using the total of all yield quantities of the operations identified. If the selection includes several process steps (workplaces), the yield quantities of all workplaces selected are totaled. It does not matter if several operations of one order are then included.

Use the application [Order-related statistic](#) to get an overview of one order only.

Detail application *Scrap ranking list (scrap reasons)*

The *Scrap ranking list (scrap reasons)* shows the scrap quantities recorded for the different scrap reasons in a graphic form.

The entries selected in the tabular detail application control the display of the bar chart. To show all entries of the table in the graphic, select the complete table. To select the complete table, click the table field in the top left corner. To select entries, we recommend to disable the option *Show yield*.

Each bar of the bar chart shows the totaled value for each scrap reason. The total is calculated using all entries selected. The bar also shows the percentage of this scrap reason in the total scrap quantity recorded in the evaluation period. This total scrap quantity is displayed in the total line of the *Scrap statistics* detail application.

Example: the detail application *Scrap statistics* shows a total scrap quantity of 1,171 in the total line for a selected period. If you select a single entry with a scrap quantity of 122, the graphic shows a percentage of 14.42.

Detail application *Scrap ranking list (workplaces)*

The *Scrap ranking list (workplaces)* shows the scrap quantities recorded for the different workplaces/machines in a graphic form.

The entries selected in the tabular detail application control the display of the bar chart. To show all entries of the table in the graphic, select the complete table. To select the complete table, click the table field in the top left corner. To select entries, we recommend to disable the option *Show yield*.

Each bar of the bar chart shows the totaled value for each workplace. The total is calculated using all entries selected. The bar also shows the percentage of this scrap reason in the total scrap quantity recorded in the evaluation period. This total scrap quantity is displayed in the total line of the *Scrap statistics* detail application.

Toolbar



Order information

Calls the [Order information](#) for the currently selected order.



Failure mode analysis (function authorization faep)

Click this button to call the [Failure mode analysis](#).



You can only call the *Failure mode analysis*, if the extension [scrst82](#) is activated.