

1 Inspect Variable Characteristics

The main role of the dialog is collecting measured values from previously selected characteristics. Added information is tolerance limits, measurement unit, target value, sample size and the used test equipment or specified test equipment group.

If the 1. measured value is collected for a characteristics and the sample size is for example 3, the field "Value no." is pre allocated with the "1". If the valued measure and optionally a comment is saved, the collection dialog is automatically closed and opens instantly after storage. The field "Value no" is now pre allocated with " ". If the inspection data could is saved successfully, a message line containing relevant information is sent right after closing the dialog and before the collection catalog is opened again. The message line is located above the characteristics list. If the data is saved the message line is highlighted in green. If it is not saved the color is pink. This can happen if the measured value has not been saved due to a violation of plausibility.

The value no. always increased by one number if the collection dialog is opened again. It might be the case that the value no. "4" is preset but the sample size has the number "3". If no more measured values are to be collected or the specified sample size has been reached, the collection dialog must be closed manually.