

1 Configuration for Throughput Batch Processing

Overview

Usage

In material and production logistics, the batch number of an input batch can be handed down to an output batch and thus make so-called throughput batch processing possible.

However, in order to enable throughput batch processing, the following configurations are required on various objects.

Machine Configuration

In the machine configuration (Master data → Workplaces/machines → Workplace configuration), the batch management in the Workplace configuration (MPL) tab is to be set to value "D".

When throughput batch processing is active on the machine, the "Automatic generation of batch number" option cannot be used, since in this case the batch number will always be handed down by the input batch.



The entry of machine cycles in combination with throughput batch processing is not used in general, since there is always a 1:1 transfer of input batches into output batches. For this reason, throughput batch recording is generally only used in connection with manual unit posting at the terminal (e.g. use in furnace, conditioning, etc.).

Configuration of Material Type

In the master data configuration (Master data → Material → Material type), the [material type](#) is to be configured in such a manner that the batch number is "handed down" and the input batch is only valid for one output batch.



- Retrograde inventory management is generally not performed for the component whose batch number is transferred as a throughput batch, since consumption is always 1:1.
- A parallel log-on of the input batch on several machines is not supported by the system.
- The entry of unknown input batches is not supported by the system.

Configuration at the Operation

The configured material type is to be entered as the material type at the operation.

The operation is to be identified as requiring batch management.

Configuration at the Operation - Component

The configured material type is to be selected as the material type at the component.



In addition to the component for which the batch number is to be handed down, other material components can be maintained at the operation. These continue to be taken into account in the usual way in the course of batch log-on and consumption recording.