

1 InspectionRequirementExport

1.1 Restriction of Data Source

1.1.1 Implementation

Purpose

The MOC cannot automatically identify which data sources are actually required for specific reports using Word reporting templates. The application can restrict the data source to export in order to reduce processing times.


Requirements

The report must be created as a template. „InspectionRequirementExport“ is the assigned export program.

Procedure/implementation

The configuration for the form must contain the following setting in the field additional parameter:
ExportData:<Abbrev. of data source 1>,< Abbrev. of data source 2>,< Abbrev. of data source 3>,...]

Example:



1.1.2 Overview of all data sources

Name of the data source	Description	Abbreviation
ReqList	Inspection requirement list	REQ
ReqListDoc	Inspection requirement related documents	REQD
QMDefectAssignedInspectionRequirementList	Inspection requirement related failures	QDAREQ
QMMeasureAssignedInspectionRequirementList	Inspection requirement related measures	QMAREQ
StepList	Inspection step list	STL
CharList_Step	Inspection step related characteristics list	CLS
OrderCharListDoc_Step	Inspection step related characteristics documents	OCLDS
ControlChart_InspectionStep	Inspection step related control chart	CCIS
ControlChart2_InspectionStep	Inspection step related control chart 2	CC2IS
Histogramm_InspectionStep	Inspection step related histogram	HGIS
QMSingleValue_InspectionStep	Inspection step related single values	QMSVIS
QMSample_InspectionStep	Inspection step related samples	QMSIS
Statistics_Step	Inspection step related statistics	STS
PointList	Inspection Points List	PTL
CharList_Point	Inspection related characteristics list	CLP
OrderCharListDoc_Point	Inspection related characteristics documents	OCLDP

ControlChart_InspectionPoint	Inspection point related control chart	CCIP
ControlChart2_InspectionPoint	Inspection related control chart 2	CC2IP
Histogramm_InspectionPoint	Inspection point related histogram	HGIP
QMSingleValue_InspectionPoint	Inspection point related single values	QMSVIP
QMSample_InspectionPoint	Inspection point related samples	QMSIP
Statistics_Point	Inspection step related statistics	STP
EMUAssignList_Req	Exception; not relevant for export.	EMUALR
CharList_Req	Inspection step for all characteristics for the inspection requirement	CLR
QMSingleValue_Req	Single values	QMSVR
Statistics_Req	Statistic	STR