

Manual

WEP Escalation Messages WEP-ESK 8.1

Version 1.0.1361

Last changed on: 19.06.2020

Copyright

©Copyright 2012 All rights reserved.

SAP® and R/3® are registered trademarks of SAP AG.

WINDOWS® is a registered trademark of Microsoft Corporation.

MPDV® and HYDRA® are registered trademarks of MPDV Mikrolab GmbH.

ORACLE® is a registered trademark of ORACLE Corporation, California, USA.

Copying and distribution of this documentation or any part thereof, for any purpose or in any form, is prohibited without prior written permission from MPDV Mikrolab GmbH.

The information contained in this documentation is subject to change without prior notice.

Contents

1	WEP Escalation Messages - Overview.....	4
2	Available Escalations	5
2.1	Failure analysis criterion generated for an inspection order (CPAUERR.INSERTED)	5
2.2	Measure generated (CMASSN.INSERTED).....	7
2.3	Formula calculation: erroneous characteristics reference in the calculated characteristics (CPAUMW.CALCULATED_CRITERIAS_GET_VARIABLE_VALUE)	7
2.4	Error while setting the calculated variable value (CPAUMW.CALCULATED_CRITERIAS_SET_VARIABLE)	8
2.5	Changed inspection severity (CDYHSTPR_DYPSCHARF_CHANGED)	9

1 WEP Escalation Messages - Overview

Purpose

HYDRA escalation management provides a framework of functions that can be used to forward events that occur or were recorded in HYDRA to individual users or user groups in real time. During the process, escalation management takes active steps to ensure users are notified.

After notification, escalation management monitors times until acknowledgment by the recipients and until escalation is concluded. Escalations can be forwarded to other users or user groups during processing.

Implementation considerations

Use escalation management for active, real-time notification of specific events around the goods receipt inspections in order to prevent failures and to increase efficiency and productivity through rapid response.

Integration

The triggered events/escalations are posted to central escalation management. This forms the framework for forwarding and following up on the triggered events.

To notify people, escalation management accesses both [User Administration](#) and [HR Master Data](#) stored in the system. Notifications can be sent out as e-mails by integrating the local mail server into the system.

Features

- Staging different escalation messages around inspection data recording.
- Event configuration: configuration of order-related events.
- Forwarding the detected events to the escalation framework.

2 Available Escalations

2.1 Failure analysis criterion generated for an inspection order (CPAUERR.INSERTED)

Escalation is triggered if a failure analysis criterion (failure type, location, cause, etc.) is generated for an inspection order.

Event	Identifiers	Description	QMS
CPAUERR.INSERTED	CPAUERR.RECTYP	Data type	Yes
	CPAUERR.BER	Area	Yes
	CPAUERR.PANNR	Inspection requirement	Yes
	CPAUERR.PAUNR	Inspection order	Yes
	CPAUERR.AFO	AFO	Yes
	CPAUERR.STPRNR	Sample number	Yes
	CPAUERR.WERTNR	Measured value number	Yes
	CPAUERR.ERRTYP	Type of error analysis entry FA (failure type) FU (failure cause] FO (failure location) VU (causer) Different entries for each type could be defined in the quality master data.	Yes
	CPAUERR.ERRNR	Number of the failure analysis entry	Yes
	CPAUERR.GEWICHTUNG	Weighting	Yes
	CPAUERR.BEM	Comment	is blank
	CPAN.FU:1 CPAN.FU:2 CPAN.FU:3 CPAN.FU:4 CPAN.FU:5	Quick user field 1 Quick user field 2 Quick user field 3 Quick user field 4 Quick user field 5 (of the inspection requirement) (Type: CHAR)	No
	CPAN.FU:6 CPAN.FU:7 CPAN.FU:8 CPAN.FU:9 CPAN.FU:10	Quick user field 6 Quick user field 7 Quick user field 8 Quick user field 9 Quick user field 10 (of the inspection requirement) (Type: LONG)	No

Event	Identifiers	Description	QMS
	CPAN.FU:11 CPAN.FU:12	Quick user field 11 Quick user field 12 (of the inspection requirement) (Type: Double)	No
	CPAN.FU:13 CPAN.FU:14	Quick user field 13 Quick user field 14 (of the inspection requirement) (Type: Date)	No
	CPAN.ATK	Article number (of the inspection requirement)	Yes
	CPAN.ATKIDX	IDX article (of the inspection requirement)	No
	CPAN.ANR	Order number (CAQ) (of the inspection requirement)	Yes
	CPAN.MNR	Machine number (of the inspection requirement) (of the sample) (Feb.2011)	???
	MNR.BEZK	Machine designation	No
	ARTIKEL.ATKBEZ	Article designation	No
	ARTIKEL.GRP	Article group	No
	CMM.OTG	Upper tolerance limit (absolute specification) (of the inspection order criterion)	Yes
	CMM.UTG	Lower tolerance limit (absolute specification) (of the inspection order criterion)	Yes
	CPAUMW.MW	Measured value	Yes
	CPAUMW.BEMERK	Comment (of the measured value)	No
	CPAUMW.PNR	Inspector ID (of the measured value)	No
	CPAUMW.KNR	Inspector badge number (of the measured value)	No
	CPAUMW.NUM:EINTTYP	Type of number entry ("NUMBER")	No
	CPAUMW.NUM:EINTNR	Number of the number entry	No

2.2 Measure generated (CMASSN.INSERTED)

Escalation is triggered if a measure has been generated.

Event	Identifiers	Description
CMASSN.INSERTED	CMASSN.MASSER	Identifier for the measure
	CMASSN.RECTYP	Data type
	CMASSN.RECREF	Assignment
	CMASSN.BER	Area
	CMASSN.KEY:1	Key field 1
	CMASSN.KEY:2	Key field 2
	CMASSN.KEY:3	Key field 3
	CMASSN.KEY:4	Key field 4
	CMASSN.KEY:5	Key field 5
	CMASSN.MASNR	Measures number
	CMASSN.MASTEXT	Measures text
	CMASSN.VERANT:TYP	Responsible - type
	CMASSN.VERANT:NR	Responsible - number
	CMASSN.STA	Status
	CMASSN.ZIELDAT	Target date - date
	CMASSN.ZIELZEI	Target time - time
	CMASSN.ELEM	corresponding workflow element
	CMASSN.BEM	Comment
	PNR	Person responsible (only if the person responsible is from the HR master data)

2.3 Formula calculation: erroneous characteristics reference in the calculated characteristics (CPAUMW.CALCULATED_CRITERIAS_GET_VARIABLE_VALUE)

An escalation is triggered if the reference to a source characteristic could not be resolved while calculating characteristics.

Event	Identifiers	Description
CPAUMW.CALCULATED_CRITERI	CPAUMW.RECTYP	Data type

Event	Identifiers	Description
AS_GET_VARIABLE_VALUE	CPAUMW.BER	Area
	CPAUMW.PANNR	Inspection requirement number
	CPAUMW.PAUNR	Inspection order number
	CPAUMW.AFO	AFO
	CMERK.BFORMEL:TYP	Level of characteristics calculation (see document on formula calculation) V - Single values S - Samples C - Characteristics
	CMERK.BFORMEL	Characteristics calculation formula
	ERR:TEXT	Error description
	VAR:NAME	erroneous variable

2.4 Error while setting the calculated variable value (CPAUMW.CALCULATED_CRITERIAS_SET_VARIABLE)

A reference to the source characteristic could be resolved while calculating characteristics. An escalation is triggered if an error occurred while inserting the calculated numeric value into the formula.

Event	Identifiers	Description
CPAUMW.CALCULATED_CRITERIAS_SET_VARIABLE	CPAUMW.RECTYP	Data type
	CPAUMW.BER	Area
	CPAUMW.PANNR	Inspection requirement number
	CPAUMW.PAUNR	Inspection order number
	CPAUMW.AFO	AFO
	CPAUMW.STPRNR	Sample number (of the calculated value)
	CPAUMW.WERTNR	Single value number (of the calculated value)
	CMERK.BFORMEL:TYP	Level of characteristics calculation (see document on formula calculation) V - Single values S - Samples C - Characteristics
	CMERK.BFORMEL	Characteristics calculation formula
	ERR:TEXT	Error description

Event	Identifiers	Description
	VAR:NAME	Name of the variables concerned
	VAR:VALUE	Value calculated for the variable

2.5 Changed inspection severity (CDYHSTPR_DYPSCHARF_CHANGED)

Escalation is triggered if the inspection severity is changed.

Event	Identifiers	Description
CDYHSTPR_DYPSCHARF_CHANGED	CPAUSP.RECTYP	Sample data type
	CPAUSP.BER	Sample area
	CPAUSP.PANNR	Inspection requirement
	CPAUSP.PAUNR	Inspection order
	CPAN.ANR	Order
	CPAU.AGNR	Operation
	CPAUSP.AFO	AFO
	CMERK.CMMNR	Characteristic number
	CMERK.MMBEZ	Characteristic designation
	CPAUSP.STPRNR	Sample
	CPAUSP.DEVICE:TYP	Device type
	CPAUSP.DEVICE:ID	Device
	CPAUSP.DEVICE:STPRNR	Device sample
	DYPSCHARF:ALT	Old inspection severity
	DYPSCHARF:NEU	New inspection severity
	CHANGE:DAT	Change date
	CHANGE:ZEI	Change time