

Manual

qs-STAT Interface for WEP WEP-QSS 8.2

Version 1.0.23049

Last changed on: 02.09.2020

Copyright

©Copyright 2020 All rights reserved.

SAP® and R/3® are registered trademarks of SAP AG.

WINDOWS® is a registered trademark of Microsoft Corporation.

MPDV® and HYDRA® are registered trademarks of MPDV Mikrolab GmbH.

ORACLE® is a registered trademark of ORACLE Corporation, California, USA.

Copying and distribution of this documentation or any part thereof, for any purpose or in any form, is prohibited without prior written permission from MPDV Mikrolab GmbH.

The information contained in this documentation is subject to change without prior notice.

Contents

1	qs-STAT Data Export for WEP.....	4
2	qs-STAT® Data Export	5
	Starting the Function	5
	Default Application Layout.....	5
	Selection of the data set.....	6
	Automatic start of qs-STAT®.....	6

1 qs-STAT Data Export for WEP

Purpose

This component enables the export of inspection data in the qs-STAT data export as DFQ file format, using comprehensive filter criteria.

Implementation notes

You should use this component if special statistical evaluations are required and the external software "qs-STAT®" by Q-DAS has been installed.

Integration

This component is based on the quality data recorded in HYDRA with regard to the variable and attributive inspection step characteristics.

Features

The following functions are available:

- Filtering of the existing data pool of in-production and goods issue inspections
- Automatic processing of filtered data for further processing in qs-STAT®
- Automatic start of qs-STAT with filtered and processed data

2 qs-STAT® Data Export


Summary

This document describes the application "qs-STAT® data export" within the Manufacturing Operation Center (MOC).

Starting the Function

Menu	Quality management --> QM evaluation --> qs-STAT® data export
Transaction code	qsstat
Function authorization	qsstat.export

Default Application Layout



Utilization

This application allows for characteristics (sample data) to be transferred to the program package qs-STAT® for further analysis. The amount of data selected can be restricted by a variety of filters based on orders, available inspection plans, characteristics and samples.

Selection criteria

At least the fields

- Area type
- Area

have to be filled out to be able request data. An error message occurs if data is requested and these two filter criteria are not filled out.

If the checkbox "summarize characteristics" is checked, all inspection results matching the filter criteria are exported as "one characteristic" to qs-STAT®. This is also the case if HYDRA inspection results are recorded based on several different characteristics.

The other filter criteria are not explained in detail here, as they are self-explanatory.

Selection of the data set

In this application characteristics can generally be identified either by the OP sequence number or the characteristic number.

If filtered by the OP sequence, a characteristic can be identified uniquely within an inspection plan. This can be useful, for example, even if an inspection plan includes several characteristics with identical characteristic number.

If filtered by the characteristic number, reports can also be started if the number and/or order of characteristics has changed over several inspection plans.

Automatic start of qs-STAT®

The user has to make sure that the file extension is connected with the correct program to start the relevant qs-STAT® program automatically after an export. If assistance is required Q-DAS (manufacturer of qs-STAT®) has to be contacted.