

1 Terminate Transport Operation

Overview

License	MPL-TRA
---------	---------

Usage

The functionality described below enables termination of an operation of a transport order and posting of the object to be transported in the target material buffer.

Prerequisite

The data base patch **dbp_mpl_transportation.hsc** must have been run.



The OP status Finished (E) must be configured in the status assignment for the order type.

Features

Input parameters:

- Transport order operation number (TRANR.ANR)
- Machine number on which the transport operation is to be logged on (TRANR.MNR)
- Target material buffer to which the object is to be posted (TRANR.TMP)
- Transport quantity (TRANR.EGR:GUT, default is target quantity of the operation)

The BAPI call TRANR.END performs the following checks:

- The transport order must be in the Running status (L).
- The target material buffer must exist.
- As an option, the staff badge number is checked if it is transmitted (KNR).

Result of BAPI call TRANR.END:

- The transport operation is terminated with the target quantity (A_AB).
- The OP status of the transport operation changes from Running (L) to Finished (E).
- The object to be transported changes to the status

Batch: Batch status = F (free), transport status = F (free)

Resource: Resource status = <Is reset to the status before start>

- Entry in history:
 - Batch:** Batch change/transfer posting in batch history
 - Resource:** Event RES_STATUS in WRM History
Transfer posting of resources (RES_UMB) in WRM History