

# 1 Analysis Selection

## Summary

|                        |                                                       |
|------------------------|-------------------------------------------------------|
| Menu                   | Master data → Quality management → Analysis selection |
| Transaction code       | asc                                                   |
| Function authorization | asc                                                   |

Analysis selection catalogs allow for the set of failure types, failure locations, failure causes, originators, and measures that are available in measurement recording to be restricted specifically.

The overall application is divided into two hierarchical levels. A master-detail grid is used for presentation. The data records of the analysis selection are created on the first level. One level below, the corresponding failure types, locations, causes, originators and measures are assigned to these data records of the analysis selection. There is a separate tab for each assignment type on this second level.

Separate function keys to create, edit or delete data records are available on each level of the master-detail grid.

## Utilization

The analysis selection number identifies the data records of the analysis selection uniquely in all QM applications in which they may be selected and assigned.

A data record of an analysis selection catalog only consists of a number and designation as well as of the flag to disable it ("inactive" field). The most crucial factor here is the possibility to assign failure types, locations, causes, originators and measures to a data record of the analysis selection.

If a characteristic is assigned an analysis selection catalog only the failure types, failure locations, failure causes, originators and measures listed in this catalog will be available for this characteristic when measured values are recorded. Consequently, the failure list, for example, can be designed in relation to characteristics.

Analysis selection catalogs are mainly used for the assignment to an inspection chart characteristic. An assignment is almost mandatory for inspection chart characteristics, as in any other case, the user may choose from the whole set of failure types of the entire master data catalog when recording measured values for this characteristic. This would make inspections confusing and too complex.

## **Integration**

Analysis selection catalogs are used in all applications dealing with characteristics. By assigning analysis selection catalogs in these applications, the selection list for failures, originators and measures is restricted for measurement recording.

## **Prerequisite**

The master data for failure types, failure locations, failure causes, originators and measures need to be maintained before this function can be used in a useful manner.

## **Selection criteria**

Selection criteria are self-explanatory and are not described separately.

## **Field descriptions**

The available fields are self-explanatory and are not explained separately.

The check box "inactive" identifies data records of the analysis selection that are no longer to be used for the definition of characteristics (of inspection plans/inspection orders).