

1 Assignment of Order Types to CAQ Areas

Overview

HYDRA menu	System administration → System settings → Area: configuration of order type
FEDRA menu	System administration → System settings → Area: configuration of order type
Transaction code	ortycaq
Function authorization	ortycaq

Purpose

Use the application "Area: configuration of order type" to configure how order types are assigned to the following CAQ objects:

- Area type
- Areas

An alternative version for generating inspection requirements and/or orders is available for every combination of "order types and area types/areas".

The alternative is entered in the field "action". The below table describes the possible alternatives and their functions. Enter additional parameters specifying the generation of inspection requirements in the field "addition".

Action	Function
PAN_AU/A_AN	The system generates an inspection requirement, once you have logged on an operation. Requirement: One inspection plan for all operations
PAN_AG/A_AN	The system generates an inspection requirement, once you have logged on an operation. Requirements: - One inspection plan for each OP - Option 1159 was created by the patch "dbp_caq_ade_integration_2_enh.hsc".
PAN_AU/A_ST	The system generates an inspection requirement, once the order status has changed.

	In the field "addition" define which changed orders statuses should generate an inspection requirement. The following combinations (source and target status) are possible: • [AUST_Q:<Source status>] • [AUST_Z:<Target status>] • [AUST_Q:P],[AUST_Z:V]
PAN_AU/AUNR_COPY	Only use this parameter for the order type "KAL". This configuration automatically generates a calibration inspection requirement if the calibration calendar includes a calibration order. Click the button "generate order" to generate the calibration order. Meet the following requirements: • Configure the calibration inspection plan as follows: ○ One inspection plan for all operations ○ One inspection step for each inspection station ○ Generate QM operations: none ○ "Inspection order + generate characteristic": when generating the inspection requirement • The inspection plan characteristics for the calibration must be planned for a machine/machine group. • Service Pack 11 or higher
empty	Leave the field "action" empty, if you do not want to generate an inspection requirement after logging on an operation. Use this option if you want to generate an order with QM operations upon generating an inspection requirement.

The following table describes the parameters of the field "addition" specifying the generation of inspection requirements. If you want to enter multiple control parameters, use a comma to separate the entries. But do not enter space characters before or after the comma.

Addition	Function
[AUNR,AGNR]	The following database fields of the database table "auftrags_bestand" link the inspection step structures with the operation structures.

	- aunr (order number) - agnr (operation number).
[AUNR]	Only the following database field of the database table "auftrags_bestand" links the inspection step structures with the operation structures. aunr (order number).
[ATK_AG]	The application uses the article of the operation to generate the inspection requirement.
[ATK_AU]	The application uses the article of the order to generate the inspection requirement.
[AUST_Q:<Source status>]	If the order switches from the defined source status to another order status, the system triggers the generation of an inspection requirement.
[AUST_Z:<Target status>]	If the order switches from any order status to the defined target status, the system triggers the generation of an inspection requirement.
[AUST_Q:P],[AUST_Z:V]	If the order switches from the defined source status "P" to the defined target order status "V", the system triggers the generation of an inspection requirement.

Integration

The application "area - order type configuration" links the BDE functions with the CAQ functions.

Requirements

You must use at least one of the following CAQ/PDV functions:

- Incoming goods inspection
- In-production inspection
- Goods issue inspection
- Initial sample inspection
- Calibration
- QM subsystem
- PDV data collection

Selection criteria

Selection criteria are self-explanatory and not described separately.

Field descriptions

Area type

Select the area type

Area

Select the area of the area type

Order type

Select the order type

Action

Define the alternative to generate inspection requirements

Addition

Define the parameters to specify the generation of inspection requirements