

1 Stock Overview TPU

Summary

--	--	--

Menu	Material management→ Inventory management→ TPU stock overview
Transaction code	stovhu
Function authorization	stovhu

Usage

The transport units stock overview is used to show the quantities of materials in the individual transport units. This can be used to determine which quantities of which material and which batches are included in which transport unit and how the transport units are currently assigned.

Integration

A pre-selection of material, transport unit and of other criteria will be shown as cumulative display of the batch/ material stock per transport unit. The display will be cumulated for each material, transport unit and batch status. Batches with a remaining quantity of 0 will not be accounted for.

Only those materials will be accounted for that are assigned to those material types, for which the "inventory management" indicator is not set to No.

Moreover, only those transport units will be accounted for, for which the "inventory management" indicator is set to "Y".

Selection parameters

The following selection criteria are available in the application:

Batch number

All materials with the selected batch number will be shown.

Batch status

This selection criterion refers to the batch status of the material. All materials with the selected batch status will be shown.

Material type

This selection criterion refers to the material type of the material. All materials with the selected material type will be shown.

Material

All materials with the selected material will be shown.

Transport unit

All materials with the selected transport unit will be shown.

If several selection criteria are used, the intersection of the selection criteria will be shown.

Field description

Calculation of the values in the stock category:

Number of batches

Quantity of batches (in line with the stock indicator set to the material type)

Quantity

Sum of yield + scrap

Unit

Unit from the configuration table TPU – material type

Yield

Quantity identified as yield that is in fact included in the "number of batches"

Scrap

Quantity identified as scrap that is in fact included in the "Number of batches"

Calc. Quantity

Quantity of material that would fit into the currently assigned transport units:

Quantity from the configuration TPU material type for this TPU x number of batches

Calc. Quantity of TPU

Quantity of TPU that would be necessary for the total quantity:

Quantity/ (quantity from the configuration TPU material type for this TPU)

The result will be rounded up to the next integer.

Batches that are not assigned to a transport unit will **not** be accounted for in this evaluation.