

Manual

Online Visualization Process Data Management Collection Rules

PDV-OVP 8.1

Version 1.0.23049

Last changed on: 02.09.2020

Copyright

©Copyright 2012 All rights reserved.

SAP® and R/3® are registered trademarks of SAP AG.

WINDOWS® is a registered trademark of Microsoft Corporation.

MPDV® and HYDRA® are registered trademarks of MPDV Mikrolab GmbH.

ORACLE® is a registered trademark of ORACLE Corporation, California, USA.

Copying and distribution of this documentation or any part thereof, for any purpose or in any form, is prohibited without prior written permission from MPDV Mikrolab GmbH.

The information contained in this documentation is subject to change without prior notice.

Contents

1	Online Visualization of Process Data	4
2	Process Trend	5
3	Process Data Monitor	7
4	Process Visualization	9

1 Online Visualization of Process Data

Overview

Purpose

The PDV-OVR function packet contains functions for online visualization in the MOC client. Connections can be established to all PDV data servers available in the HYDRA network and that can be accessed from the infrastructure. The data from these servers is visualized online. A definition of which data can be displayed is made by the logical channels and the collection requests currently running on the machines.

Existing display instruments and a trend graphic are available for visualizing. Special layouts for visualizing systems or system components can be integrated into the system using the suitable editors, thus creating what is effectively a machine cockpit with which to view system process data.

Integration

This function packet requires a machine interface for data collection in the HYDRA process communication controller (PCC), the data server integrated into it, the network infrastructure and the basic PDV-PDM package including the collection rules.

Features

- Permanent display of process data for one or more machines and systems. With the proper license (development license is required), system images can be generated automatically or created by HYDRA customizing. incl. runtime license for process visualization.
- Online measured value display with predefined pointer graphic for a machine. The characteristics to be displayed can be selected interactively.
- Measured value displayed online as trend line for a machine. The characteristic to be displayed can be selected interactively. Progress and the last measured values for this characteristic are visualized online as a continuous trend graphic.

2 Process Trend

Summary

Menu	Quality management → Process data collection→ Process trend
Transaction code	tpd
Function authorization	tviewpd

The process trend is used to perform process monitoring in quality management.

Usage

The collection processes defined through the collection rules allow to visualize the defined characteristics online. The characteristics identified for visualization are provided to the network by the related data servers. The visualization components existing in this application connect to these servers and will show the measured values online.

The presentation is made as trend line.

Integration

The display functions will visualize the data of the involved shop floor servers in accordance with the collection specifications . In doing so, always a certain amount of historic measured values will be shown and updated by a current value.

Requirements

It must be possible to reach the shop floor servers involved in the network and they must be configured for the presentation of the process data. A registration service (yellow pages to visualize process data online) must be set-up in the network. The display layouts must be available locally or on the server.

Selection parameters

The following selection criteria are available in the application:

Workplace

The pool application workplace can be used to select the desired workplace.

Process parameter

The process parameter drop-down list offers a selection of process parameters.

Workplace

The pool application workplace can be used to select the desired workplace.


Process parameter

The process parameter drop-down list offers a selection of process parameters.

Field descriptions

Detail applications

The visualization area is used to show the graph of the selected workplace and the individual selected process parameters.



3 Process Data Monitor

Summary

Menu	Quality management → Process monitoring → Process data monitor
Transaction code	mvpd
Function authorization	mviewpd

The process data monitor is used for the process monitoring in quality management.

Usage

The collection procedures defined by the collection rules also allow the online visualization of defined characteristics. The characteristics identified for visualization are provided by the respectively related data servers in the network. The display components existing in this application are connected to these servers and display the measured values online.

The display takes the form of a vector diagram.

Integration

The data of the participating shop floor servers is visualized by the display function based on the specifications of the collection requests. A certain number of measured values from the past are always displayed as well and are part of a continuation including the current value.

Requirement

The participating shop floor servers in the network must be accessible and they must be configured for the presentation of process data. A registration service (yellow pages for process data online visualization) must be set up in the network. The layouts for the display must be available locally or on the server.

Selection criteria

The following selection criteria are available in the application:

Workplace

In the workplace pool application, the desired workplace can be selected.


Process parameters

The process parameters drop down list includes a selection of process parameters.

Field descriptions

Detail applications

The selected process parameters pertaining to the selected workplace are displayed in the graphic of the visualization area.



4 Process Visualization

Summary

Menu	Quality management → Process analysis → Process visualization
Transaction code	vispd
Function authorization	visupd

Process visualization is used to monitor the process data in quality management.

Usage

The collection processes defined through the collection rules allow to visualize the defined characteristics online. The related data server provides the characteristics identified for visualization to the network. The visualization components existing in this application connect to these servers and will show the measured values online.


It is also possible to select the display layout and to integrate customized display layouts.

Integration

The display functions will visualize the data of the involved shop floor servers in accordance with the collection specifications.


Requirements

- It must be possible to reach the shop floor servers involved in the network and they must be configured for the presentation of the process data. A registration service (yellow pages to visualize process data online) must be set-up in the network. The display layouts must be locally available. If they are not saved locally they will be transferred from the directories of the corresponding HYDRA server to MOC upon the user's request. To do so, the button "Load PDV layouts from server" must be used.



In order to load the data from the server, the HYDRA path "PDVLAY" must be configured. HYDRA paths can be created using the MOC system under "System administration-> System settings -> Paths".

URL path = ./<system no.>/custom/



Selection criteria

The following selection criteria are available in the application:

Workplace

The pool application workplace can be used to select the desired workplace.

Process parameter

The process parameter drop-down list offers a selection of process parameters.

Field descriptions

Detail applications

The visualization area is used to show the graphs of the selected workplace and the individually selected process parameters. The display offers different visualization options that can be selected from the drop-down layout list. Several standard layouts are stored here but also special machine layouts created for the installations and machines.

Examples:

