

# Handbuch

## Sequenzanalyse PDV-SQA 8.3

Version 1.0.23049

Letzte Änderung: 02.09.2020

## Copyright

©Copyright 2020 Alle Rechte vorbehalten.

SAP® und R/3® sind eingetragene Warenzeichen der SAP AG.

WINDOWS® ist eingetragenes Warenzeichen von Microsoft Corporation.

MPDV® und HYDRA® sind eingetragene Warenzeichen der MPDV Mikrolab GmbH.

ORACLE® ist ein eingetragenes Warenzeichen der ORACLE Corporation, Kalifornien, USA.

Weitergabe und Vervielfältigung dieser Dokumentation oder von Teilen daraus sind, zu welchem Zweck und in welcher Form auch immer, ohne die ausdrückliche schriftliche Genehmigung durch MPDV nicht gestattet.

Alle Rechte vorbehalten.

# Inhaltsverzeichnis

|   |                        |   |
|---|------------------------|---|
| 1 | Sequence Analysis..... | 4 |
| 2 | Sequence Analysis..... | 5 |

# 1 Sequence Analysis

## Overview

### Purpose

The product PDV-SQA includes functions for the graphic display of a sequence of process parameters.

### Integration

To display sequence curves, you must record a process parameter and a process parameter that is defined as TAG type (alphanumeric tag).

### Features

This product provides the following functions:

- Presentation of the process values saved as sequence (set of curves)
- Possible import of a reference curve for a process parameter

## 2 Sequence Analysis

### Overview

|                        |                                                           |
|------------------------|-----------------------------------------------------------|
| Menu                   | Quality management → Process analysis → Sequence analysis |
| Transaction code       | pdsa                                                      |
| Function authorization | pdsa                                                      |

### Purpose

You use the sequence analysis to display a set of curves. The display includes several sequences of a process parameter progression. A sequence is the period of time between two specified separators. A process parameter of data type "tag" is used as separator.

### Requirements

To display sequence curves, you must record a process parameter and a process parameter that is defined as TAG type (alphanum. tag).

The TAG type value is used in the sequence analysis to identify the limits of the separate sequences. The sequence therefore is the period of time between two recorded values of the process parameter that is used as TAG type.

#### Note:

The sequence analysis requires that all relevant process data is linked to tag contents (e.g. serial numbers). A curve is drawn for the time domain that is continued as long as a TAG content does not change its value. If no TAG value is assigned to one or several process values, these process values are not used in the evaluation.

### Selection criteria

The application provides the following selection criteria:

#### Process parameter

This selection criterion specifies the process parameters. The measured values of these process parameters are then displayed. You can select a process parameter from the list.

#### TAG type

This selection criterion refers to the tag type for which the measured values have been recorded.

### Workplace

This selection criterion refers to the workplace where the measured values have been recorded.

### Number of curves

This selection field specifies the number of sequences displayed in a chart. The default value five is preset in this selection field. You can enter other integer numeric values.

### Time domain

This selection criterion defines the evaluation period for which the measured values are displayed. You can specify the time domain to the millisecond. When you open the application, the time domain is preset with a time domain from opening time to eight hours into the past.

#### Note:

For performance reasons, the data query for the sequence analysis is restricted to a maximum of 10,000 data points.

You can increase the maximum number of data points via INI configuration. If you increase the maximum number of permitted data points beyond 10,000, this has a negative effect on the evaluation speed and is the responsibility of the customer.

INI configuration: "SYS\_WS\_PARAM"

Section: "ANALYSISPROCESSDATA.LISTBYWORKPLACELASTTAGVALUESDECIMALBASED"

Key: "CORE.TOP\_COUNT")

### Toolbar



#### Import reference curve

You use this function to import a data file that includes a reference curve. The file size is limited to 1 megabyte.

### Detail applications

In the sequence chart, a tooltip is shown at the relevant position of the cursor including the following information:

- Point in time within the sequence
- Measured values of the curves displayed

- Upper tolerance limit
- Upper process action limit
- Lower process action limit
- Lower tolerance limit