



TROUBLE SHOOTING REPORT

PSMD (SABHAN)

Ref. No:	92/05/21	Date:	te: 10/05/2021		Prnt.Time		10:16
Substation:	SHUWAIKH IND-A		<u>N</u>	<u>lake:</u>	SIE	<u>P.M:</u>	26/03/2019
			<u>N</u>	<u> Iaint:</u>	SIE	Comm:	09/23/1982
Equip./Unit A	Affected: 30MVA Tr.# 2						
Nature of Fault: LT is failed to open by supervisory. PME has to follow.							
Concerned Group & Engr: Pme/ ahmad yousef Technicians:- 1-							
	Section Head :				2-		
Action Take	en:						
Contacted Dcc for mentioned issue. They said there is preventive maintenance is in progress. Therefore, they							
will fo	ollow.	_			-		
DCC II	nformed all clear						
Consormed C	Group & Engr · Ahmad yo	ousef			7	Data	11/5/2021
	Group & Engr: Anmad yo	4		•		Date:	1 1/ 3 / 2021
Director:			;	Section	Head:		