



## TROUBLE SHOOTING REPORT

PSMD (SABHAN)

Ref. No:	48/05/21		Date:	04/05/2021		<u>P</u>	<u>rnt.Time :</u>	11:43
<b>Substation:</b>	MINAA	L ZOUR-B		<u>M</u>	ake:	MIT	<u>P.M:</u>	18/10/2015
				<u>M</u>	aint:	SIE	Comm:	03/19/1986
Equip./Unit Affected:								
Nature of Fault:  DC supply appearing / dis appearing since 14/04/21, SME Yousuf Shohel (M # 94939952) checked on 03/05/21 and did not find any problem from S/G side. Also, 33kV G/Alarm is appeared during his checking. PME & SME can check together.								. Also,
Concerned Group & Engr: Salem R Alenezi Technicians:- 1-								
Section Head:					2-			
Action Taken :								
33kv G/A now clear								
there was flag touched the panel								
now is ok and alarm is Clear								
HOW IS ON AIR MAITH IS ORAI								
Do cupply come from SIMC control								
Dc supply came from SWG control								
and inication SWG should follow								
Concerned G	Froup & Eng	r :					Date:	5/5/2021
Director ·				S	ectio	n Head :		