



TROUBLE SHOOTING REPORT

12:52 Prnt.Time: Make: <u>P.M:</u>

84/05/21 09/05/2021 Ref. No: Date: SABAH AL SALEM-G **Substation:** 03/20/2016 Comm: **Maint:** 11kV Panel # 1 Equip./Unit Affected: Prot. clearance is required for the mentioned panel. Please check the attached Nature of Fault: letter from Dist. Dept. Technicians:- 1- Mohammad almittsawi Concerned Group & Engr: Mishari altuwari 2-Abdullah alamairi Section Head: Action Taken: ·Visit substation for protection clearance for mentioned feedertest all protection relays found clear. Dcc-informed... Concerned Group & Engr: Date:

Section Head:

Director: