lyft | CHICAGO

VEHICLE INSPECTION

LYFT DRIVER INFO

ALL FIELDS ARE MANDATORY

Javier Galindo Sierra
LYFT DRIVER NAME

javier_sierra25@hotmail.com
EMAIL ADDRESS

EN85143
LICENSE PLATE #

3VV2B7AXXMM068012
VIN

VOLKSWAGEN
VEHICLE MAKE

Tiguan
VEHICLE MODEL

2021
VEHICLE YEAR

Javier G
LYFT DRIVER SIGNATURE

+13123887972
LYFT DRIVER PHONE NUMBER

VEHICLE INSPECTION CHECKLIST

	INSPECTION POINT	PASS	FAIL
1.	**Foot brakes**	☑	☐
2.	**Emergency brake (parking brake)**	☑	☐
3.	**Steering mechanism**	☑	☐
4.	**Windshield**	☑	☐
	Large crack	☑	☐
	Small crack	☑	☐
5.	**Rear window and other glass**	☑	☐
6.	**Windshield wipers**	☑	☐
7.	**Headlights**	☑	☐
8.	**Tail lights**	☑	☐
9.	**Turn indicator lights**	☑	☐
10.	**Stop lights**	☑	☐
11.	**Front seat adjustment**	☑	☐
12.	**Doors (open, close, lock)**	☑	☐
13.	**Rust free**	☑	☐

	INSPECTION POINT	PASS	FAIL
14.	**Horn**	☑	☐
15.	**Speedometer**	☑	☐
16.	**Bumpers**	☑	☐
17.	**Muffler and exhaust system**	☑	☐
18.	**Tires, incl. tread depth, minimum 3/32"** (inside / center / outside)	☑	☐
	Left front 6/32 6/32 6/32	☑	☐
	Right front 6/32 6/32 6/32	☑	☐
	Left rear 6/32 6/32 6/32	☑	☐
	Right rear 6/32 6/32 6/32	☑	☐
19.	**Interior and exterior rear view mirrors**	☑	☐
20.	**Safety belts for driver and passenger(s)**	☑	☐
21.	**Drivetrain, including the transmission and universal joints**	☑	☐
22.	**Axles and wheels including ball joints**	☑	☐

GENERAL COMMENTS

VEHICLE INSPECTION (Circle One) **PASS** **FAIL**

(One failed check mark makes for an overall failed Vehicle Inspection)

Applicant - Please note that a failed vehicle inspection form will be reviewed before a final decision is made.

TO BE COMPLETED BY INSPECTOR

Car Care Center
COMPANY NAME

John Grey
INSPECTOR NAME

3417 J St, CARD3157416
COMPANY/FACILITY ADDRESS

08/29/2026
INSPECTION DATE (document expires one year from this date)

John
INSPECTOR SIGNATURE

This inspection form reflects a 22 point inspection on the date of the inspection listed above. For the purposes of this inspection, the wheels were not removed from the vehicle, and the vehicle was not put on a lift.