<b>器の</b> に 一					
COLUMN MARK  COLUMN SCHEDULE REFER TYPICAL COLUMN ELEWITON FOR THES AND LAP INFO.	B3 TO B2 fc'=8ksi	B2 T0 B1 fc =8ksi	B1 T0 LG fc'=7ksi	LG TO GF fc'=7ksi	GF TO 1st fc'=7ksi
C1	8	VERI. BAR: 26/8	VERI. BAR: 26/8	VERT. BAR: 26/8	
C2	4-6°	3-0°	4-6-6-6-6-6-6-6-6-6-6-6-6-6-6-6-6-6-6-6	VERT. BARE 26/8	3-0°
C2A	VERT. BAR: 42410	VERT. BAR: 42#10	VERT. BAR: 42410	VERT. BAR: 32/10	VERT. BAR: 3649
C2B	VERT. BAR: 60410	VERT. BAR: 60410	VERT. BAR: 60410	VERT. BAR: 60/10	VERT. BAR: 64400
C2C	VERI. BAR: 46,88	WEI. BAR: 148	VERT. BAR: 46-6	VEXT. BASE 45/8	VERT. BAR: 46/8
C2D	VERT. BAR: 26/8	VERT. BAR: 2648	VERT. BAR: 2648	VERT. BARE 26/8	VERT. BAR: 62/10
C2E	4-6" VERI. DAR. 26/8	4-6* 4-6* 4-6* 4-6* 4-6* 4-6*	4-6'	VERT. DAGE 26/48	3-d 
C2F	4-6" VERI. BAR: 56410	VERT. BAR: 5640	VERT. BAR: S640	VERT. BAR. 40910	5-0°  FRI. BAR: 3498
C2G	VERT. BAR: SOMO	VERI. BAR: SOMO	VERI. BAR: SOMO	VERT. BAR: 40/10	VERT. BAR: 34/10
С2Н	VERT. BAR: 29410	VERT. BAR: 28410	VERT. BAR: 29410	VERT. BAR: 26/10	VERT. BAR: 40/10
C2J	VERT. BAR: 42410	VERT. BAR: 42/10	VERI. BAR: 42400	VERT. BAR: 29/10	VERT. BAR: 40/10
					<u> </u>