The MPU6050 is 6 DOF sensor

We can communicate with it with the I2C protocol.

Then we made functions with the wire library.

We set the registers of it to the needed values

Then we calibrate the values to calculate the offset

We get the right value

Then converting it to degrees to check our condition