



Data Set Name: abyss.tahiti-20221023-asset_labelling-md-tls
Subject: Most Frequent Errors



Bridles: Vertical parts of bridles (red boxes) are supposed to be labeled as vessels.





Victaulic Coupling: Should be labeled as a line, as it is used to connect 2 pipes and not to support them.



Pipe Supports: Only U-Supports, Dummy Legs, and Spring Pipe Supports should be classified as pipe supports. In this case (the red box) should not be labeled.



Vessels: Shell and tube heat exchangers (red box) were labeled as lines in multiple images, they should have been classified as vessels.



Bleed Rings: Middle section of a bleed ring should also be labeled as a flange as indicated in the SOP.



Middle silver section of the bleed ring is part of the flange and does not require a separate label of line.