

Incident ID: INC-204

Equipment:

Pump P-101

Description:

Pump temperature exceeded 95°C.

Immediate Action:

Emergency shutdown initiated.

Suspected Cause:

Cooling line blockage.

Status:

Under Investigation.