

Inspection Date:

15 July 2026

Equipment:

Pump P-101

Observations:

- ✓ Minor corrosion near outlet flange
- ✓ Oil leakage observed
- ✓ Bearing temperature higher than normal

Recommendation:

Schedule preventive maintenance within one week.