

Equipment: Pump P-101

Date: 12 July 2026

Issue:

High vibration detected.

Action Taken:

Bearing lubrication performed.

Result:

Vibration reduced by 30%.

Engineer:

John Smith