POST LAB 7

Ki = 9

Kp = 9

When the parameters were high, the motor speed first over shoot above target rpm and then reached the actual target.

When it was less, it reached the target rpm gradually.