English V







3D printers

Materials

Parts & Accessories

Software

3D Models

English forum Recent Posts Announcements English forum > Original Prusa MK3.5 > Hardware, firmware and software help MK3.5 -Failed Hotend temperature test/

MK3.5 -Failed Hotend temperature test/

Page 1 / 2 Next >

■ Last Post

RSS 3





MK3.5 -Failed Hotend temperature test/


Hi,


I have updated from MK3S+ to MK3.5. Unfortunately, the final temperature test for the hotend failed. The nozzle temperature should reach 290°C in approx. 1 minute (seems too fast!) The temperature reached was approx. 180°C.I have since replaced the thermistor and the heating cartridge, but same result - test failed. Asked Prusa via live chat, but no solution so far...Does anyone have reliable information about the duration and temperature of the Hotend test?

Furthermore, I have a problem with the print image after the update; the adhesion on the print bed is great, but the distances between the individual strings are too wide and do not adhere to each other (see picture). No idea if that is a firmware or hardware issue (difference between MK3.5 and MK3.9/MK4 are also in range of step motors; no idea about it).

Thanks for your comments! 😊







• Log in to be able to post





Posted: 12/03/2024 3:22 pm



Printitou3D
(@printitou3d)

. 2

Active Member



RE: MK3.5 -Failed Hotend temperature test/

HI,

Same here after upgrade to MK3.5. And no solution from support after some test but it think it's from the firmware and ask me to wait an update.

But I can print with hotend selftest KO.

Concerning your first layer calibration, mine is like your picture 3.

• Log in to be able to post





Posted: 16/03/2024 6:50 am

English v



Login



JoanTabb

(@joantabb)



Veteran Member

Moderator



that print looks like first layer calibration needs re running, and live Z moving closer to build plate (larger negative number)

Joan

I try to make safe suggestions, You should understand the context and ensure you are happy that they are safe before attempting to apply my suggestions, what you do, is YOUR responsibility. Location Halifax UK

• Log in to be able to post





Posted: 16/03/2024 3:06 pm



cwbullet

(@cwbullet)



Member

RE: MK3.5 -Failed Hotend temperature test/

One thing that it might help for you to post:

What hotebd, which brand of a thermistor, which brand of heat cartridge?

I can assume you are using a V6 and Prusa-purchased products, but that might be incorrect.

Chuck H

3D Printer Review Blog

1 Log in to be able to post





Posted: 16/03/2024 3:44 pm



JeHa_66

(@jeha_66)



Active Member



Topic starter answered:

RE: MK3.5 -Failed Hotend temperature test/

Hi Joan,

I have made first layer calibration several times; the line prints (Z-pattern) are really ok (good adhesion) also the border of the plate print is very good, only the lines inside the plate are to wide/or to thinn so that no connection between them can be reached. Could it be that not enough material is used?

Log in to be able to post





Posted: 16/03/2024 4:24 pm

Topic starter answered:



Login



● JeHa_66

(@jeha_66)



Active Member



Right, I am using my original stuff from MK3S+ (it worked well in the old configuration before upgrade to MK3.5)

Log in to be able to post





Posted: 16/03/2024 4:26 pm

Hi,



JoanTabb

(@joantabb)



Veteran Member


Moderator



RE: MK3.5 - Failed Hotend temperature test/

have you tried lowering Live Z? to squeeze the strings to a wider format? joan

I try to make safe suggestions, You should understand the context and ensure you are happy that they are safe before attempting to apply my suggestions, what you do, is YOUR responsibility. Location Halifax UK







Posted: 16/03/2024 8:25 pm



JeHa 66

(@jeha 66)



Active Member



Topic starter answered:

RE: MK3.5 -Failed Hotend temperature test/

Posted by: @joantabb

have you tried lowering Live Z? to squeeze the strings to a wider format?

joan

Just completed additional fine-tuning. Problem solved. Thanks! 씥



• Log in to be able to post





Posted: 16/03/2024 8:51 pm



RE: MK3.5 -Failed Hotend temperature test/

Hello,

Can you explain what are your additionnal fine tuning you have done? Because, i ve still same problem about hotend temp calibration and first







For the first layer, I adjust z offest to have perfect line, but I notice the nozzle back up on the left of my bed and i have the same result that your picture. I don't understand why.

Tks

• Log in to be able to post





Posted: 17/03/2024 11:02 am



Printitou3D (@printitou3d)



Active Member

RE: MK3.5 -Failed Hotend temperature test/

For all user with same problem, i have found github article about first layer issue on MK3.5:

https://github.com/prusa3d/Prusa-Firmware-Buddy/issues/3772





• Log in to be able to post

Posted: 17/03/2024 12:03 pm



jimD (@jimd)



Trusted Member

RE: MK3.5 -Failed Hotend temperature test/

I just finished converting a working mk3s+ to a 3.5 that can't pass the hotend self test. I have original prusa hotend parts and I flashed the latest firmware - 5.2.2, like several others the hotend gets to about 169C. Has anyone figured a solution to this problem which I think is firmware related given the printer had been working flawlessly as a MK3S+?

• Log in to be able to post





Posted: 22/03/2024 10:52 pm



Printitou3D

(@printitou3d)



Active Member



RE: MK3.5 -Failed Hotend temperature test/

My hotend selftest is passed adding a silicon socks on heat block.

You can try this

Posted by: @jimd

I just finished converting a working mk3s+ to a 3.5 that can't pass the hotend self test. I have original prusa hotend parts and I flashed the latest firmware - 5.2.2, like several others the hotend gets to about 169C. Has anyone figured a solution to



Login

Log in to be able to post





Posted: 22/03/2024 11:02 pm



Topic starter answered:

MK3.5 -Failed Hotend temperature test - problem solved

Hi,

have received firmware update from PRUSA support

https://github.com/prusa3d/Prusa-Firmware-Buddy/releases/tag/v5.2.2

Before starting the test I applied some thermal paste to the heater/thermistor and - hurray! - be able to complete the tests successfully. @



• Log in to be able to post





Posted: 23/03/2024 9:32 am




jimD



RE: MK3.5 -Failed Hotend temperature test/

I removed the thermistor and added thermal paste, replaced and it still fails the hotend test. I watched the screen during the test and the temp seemed to be climbing at > 1 degree per second up to about 164C when it indicated failure. The temp did climb up to 167C before beginning to cool down. Thanks for the suggestion,







Posted: 23/03/2024 6:59 pm



jimD

(@jimd)



Trusted Member

RE: MK3.5 -Failed Hotend temperature test/

Since I already had some thermal paste, I tried it and the test still fails. Where do I buy a silicone sock to fit a stock prusa hotend? I'll try that unless someone from prusa has a better recommendation. Thanks for the suggestion.









Login



Printitou3D

(@printitou3d)



Active Member



RE: MK3.5 -Failed Hotend temperature test/

I have bought mine on Amazon.

Fit perfectly on E3DV6 hotend.

https://www.amazon.fr/dp/B07SSTL93R? ref=ppx_yo2ov_dt_b_product_details&th=1

In orange ୱ


Posted by: @jimd

Since I already had some thermal paste, I tried it and the test still fails. Where do I buy a silicone sock to fit a stock prusa hotend? I'll try that unless someone from prusa has a better recommendation. Thanks for the suggestion.

• Log in to be able to post









Clinton

(@clinton-2)



Active Member



RE:

I had the same problem, I did all the usual things including contact support, who were extremely helpful but did not have a solution.

Upgraded to the new firmware 5.2.2 and tried again. Failed in exactly the same way but the screen asked me if I wanted to change the nozzle type. One of the options was for a silicone sock, changed to that and it went through the configuration, no problem.

It should be noted although I changed the nozzle configuration to say I have a silicone sock fitted, there is no silicone sock on the machine.

So printer now fully functional and fully passed its configuration.

• Log in to be able to post





Posted: 28/03/2024 6:26 am



RE: MK3.5 -Failed Hotend temperature test/

Thanks, lying about the nozzle type got me past the hot end check. Hopefully Prusa will fis the firmware to allow me to specify a stock hot end without the sock,



• Log in to be able to post















Posted: 29/03/2024 6:42 pm



RE: MK3.5 -Failed Hotend temperature test/

do you have a heat sock on your hot end if so take it off that's what i had to do to mine


















jimD

(@jimd)

Trusted Member



RE: MK3.5 -Failed Hotend temperature test/

I found the root cause of my problem. The 3,5 printer was an upgrade from a 3S+. As I said before I had to lie about having a sock on the extruder to pass the initial hotend temperature test. On my first print I got an error on the hot end fan not turning and went to the after setup fan test. It asked if the hot end fan was turning. Nope. I think it said to check the wiring to see if I had plugged the wrong fan into the wiring harness, It turns out that I did and plugging them in to the correct connector fixed my problem. Prnter now works as designed.



• Log in to be able to post





Posted: 11/04/2024 12:05 am

Page 1 / 2





≡ All forum topics


Previous Topic

Next Topic >

Topic Tags: hotend temperatur test fa (1)







Blog



Flash Contes ts Theme: Fridge Repairs



Practic al movie effects: Sara Villarea 1& Studio Gillis

Prusa Firmwa re Dev Diary -Regres sive Extrusi on Previe



Newsletter

Signup and get our monthly squeeze on updates, blog, printables and much more.

E-mail

I would like to receive the e-book "Basics of 3D Printing" as a gift

By clicking, you agree to receive our newsletter.

Subscribe

This site is protected by reCAPTCHA Enterprise and the Google <u>Privacy Policy</u> and <u>Terms of Service</u> apply.





2.9.1:

Smarte





Printin
g &
Strong
er
MultiMateria
I
Interloc
king

E-shop

3D Printers
Printer Upgrades
Accessories
Prusa Merchandise

Printa	Com	Help	Softw	Comp
bles	munit		are	any
	У	Prusa		
3D		Help	Prusa	About
Model	World	Prusa	Slicer	Us
S	Мар	Acade	Prusa.	Blog
3D	Forum	my	арр	Press
Desig	User	3D	Prusa	Timeli
n	Group	Printin	Conne	ne
Conte	S	g	ct	Conta
sts	Events	Calcul	Driver	ct Us
Weekl		ators	s and	
y 3D			Softw	
Prints			are	
General Terms and Conditions				

General Terms and Conditions of Use of the PRUSA Websites

Privacy Policy

Information about cookies

Status Page

General Terms and
Conditions
| General Terms and
Conditions of Use of
the PRUSA Websites
| Privacy Policy
| Information about
cookies
| Status Page