

- Take remaining smooth rods and compare their length. For X-axis you need longest rods (370 mm).
- Linear bearing (3x)
- Permanent marker (1x) not included in the kit
- Several paper towels to wipe oil and grease from the bearing surface.

