

- X-axis is done!
- Check the final look, compare it to the picture.
- Checked everything? It's time for: 4. Z-axis assembly.

