

- For the following steps, please prepare:
- Y-belt-idler (1x)
- M3x18 screw (1x)
- ▲ M3x10 screw (2x)
- M3nN nyloc nut (1x)
- M3n nut (2x)
- 623h bearing housing (1x)

