

- 8
- ▲ Now, the Z-axis is done too!
- Check the final look, compare it to the picture.
- Checked everything? It's time for: 5. E-axis assembly.

