

- For the following steps, please prepare:
- M3x18 screw (1x)
- ▲ M3x10 screw (1x)
- M3nS nut (2x)
- M3n nut (2x)
- Steel ball (1x)
- Magnet 10x6x2 (1x)
- Magnet 20x6x2 (1x)

