

- For the following steps, please prepare:
- X-end-motor (1x)
- X-end-idler (1x)
- Linear bearing (4x)
- The list continues in the next step...

