

- ▲ For the following steps, please prepare:
- X-carriage (1x)
- M3n nut (2x)
- ▲ M3nS nut (4x)
- IR-sensor cable (1x)

