I TO P & P TO I CONVERTER TRAINER KIT

PROCESS DESCRIPTION:

Components:

- 1. Supply Sensitivity: 0.025% span per % supply pressure change.
- 2. Accuracy: 0.5% FS
- 3. Zero Adjustment: 5% FS, Span Adjustment: 20% FS
- 4. Input Resistance: $<300 \Omega$
- 5. Media: Oil-free, clean, dry air filtered to 25 μm
- 6. Recommended Supply Pressure: 25 to 30 psig (filtered air)
- 7. Max Supply Pressure: 80 psig (for IP210-X120: 135 psi)
- 8. Min Supply Pressure: 10 psi above maximum output pressure.
- 9. Failure Mode: Upon electrical failure, the signal pressure falls tobleed pressure
- 10. Pressure Port: 1/4 FNPT
- 11. Electrical Connection: DIN 43650 with screw terminals included
- 12. Output: 4 to 20mA DC

