

Quality Notice

To all AT Line Operators

<u>Jumbos for Flowstrip – Splices (instruction WI07A-043)</u>

We have had a recent complaint from Flowstrip, due to delamination, material ripping out and poor appearance. The complaint relates to a 50 metre section that was found in jumbo roll batch 14775/4 made on 01/06/2011. It is understood that the affected material was found in the vicinity of a splice contained within this jumbo roll. Below photo refers:



Can sufficient material be pulled through, prior to making the splice.

Thank you for your assistance in this matter.

Dated: 01/07/2011 Signed:

P. Ward - Quality Assurance Officer (Scapa Ashton Site)