

Report 8D

Generated By: Seb Houle Generated On: 06 Jul 2011

I. COMPLAINT INFORMATION

Origination Date	27 Jun 2011		
Sales Name	Jeff Gorman	Sales Office	Windsor
Telephone	NULL	Fax Number	NULL
Email	amy.stack@scapa.com		
Customer Complaint Ref			
Customer Name	Valley Industrial		
SAP Customer Number	128100	Customer Order N°	
Customer Part Number			
1) Invoices And Items	s On Complaint		
(a) SAP Invoice Number	9700035523	Invoice Date	17 Feb 2011
- Material	165332	Batch	WIN0015538
	Material Description		
	U873 RW .5IN X 108FT (72 ROLLS/BOX)		
(b) SAP Invoice Number	9700035719	Invoice Date	23 Feb 2011
- Material	165332	Batch	WIN0015538
	Material Description		
	U873 RW .5IN X 108FT (72 ROLLS/BOX)		

2) Problem Description

Despite your assurances that the adhesive was identical to the T002, our customers have found the U873 to be unusable. The main complaint is that it is too tacky, gums up the dispenser guns as well as the material they are trying to work with.

Disposal of 125 cs approved by Mike Muchin:

Let's credit the 125 cases of U873 and ask Valley to dispose of it.

Actions	Requested	From	The	Customer

3) Containment Actions

II. EVALUATION AND ACTION No Sample/photo Received Date Process Owner Seb Houle Team Leader shoule Is Complaint Valid? Yes Return The Goods No Dispose The Goods Yes Comments 1) Analysis U873 is not identical to T002, information presented to the customer was likely a result of miscommunication. Disposal of material by customer has already been approved by Mike Muchin. Author Seb Houle 30 Jun 2011 Date 2) Root Causes Miscommunication to the customer indicated that the material was similar (and/or equivalent to T002), this in turns to have been a misunderstanding, in believing that U873 was similar (and/or equivalent to TD200). However, U873 is substantially similar to neither of these, it is most similar to UP2040RW (with a thinner liner). 06 Jul 2011 Author Seb Houle Date 3) Possible Solutions Author Date 4) Implemented Perm Corrective Actions Sent out notice to Sales individual to clarify the equivalency (or lack thereof) of the several materials. Additionally, production of U873 is not likely to continue, thereby eliminating the ability to confuse the material.

Author Seb Houle Date 06 Jul 2011

Estimated Date Implementation Date

Validation Date

5) Corrective Actions Validation

Author Date

6) Preventive Actions

Author		Date				
Estimated Date		Implementation Date				
Validation Date						
Validation Date						
7) Review Of Docum	entation					
•						
(a) MSR						
	No					
Reviewed?	No					
Reference		Date				
receive		Bate				
(b) Flow chart, control plan	n, work inspection instructions					
Reviewed?	No					
Reference		Date				
Releielice		Date				
(c) FMEA						
Reviewed?	No					
Reference		Date				
(d) Customer and differentian						
(d) Customer specification						
Reviewed?	No					
Reference		Date				

8) Congratulate The Team