

# Rapport 8D

Généré Par: Sylviane Carras Généré Le: 01 Jul 2011

## I. COMPLAINT INFORMATION / IDENTIFICATION DE LA RECLAMATION

Date De La Réclamation	27 Jun 2011		
Nom correspondant commercial	Paul Bican	Sales Office (Bureau Commercial)	Valence
Téléphone	+33 (0)4 66 20 00 26	No. Fax	-
Email	paul.bican@scapa.com		
Référence réclamation client			
Nom Du Client	Nexans France Paillart		
Numero De Client SAP	105187	N° Commande Client	
Rfrence Article Client			
1) Factures Et Article	es Sur La Réclamation		
(a) Numéro De Facture SAP	9200298036	Date De Facture	03 Jun 2011
- Matériel	137461	Lot	
	Description Produit		
	SFR10/103 Nat 30mmx800m&76idx370-4000	d	
- Matériel	151205	Lot	
	Description Produit		
	SFR10/103 Nat 35mmx800m&76idx370-400c	d	
- Matériel	137583	Lot	
	Description Produit		
	SFR10/103 Nat 40mmx800m&76idx370-400c	od	
- Matériel	137461	Lot	
	Description Produit		
	SFR10/103 Nat 30mmx800m&76idx370-400c	d	1

- Matériel	151205	Lot	
	Description Produit		
	SFR10/103 Nat 35mmx800m&76idx370-4006	od	
- Matériel	160260	Lot	
	Description Produit		_
	SFR10/103 Nat 25mmx800m&76idx370-400	od	

### 2) Description Du Problème Identifié Par Le Client

the weight of boxes are too heavy. infact the boxes are handled manually.

nexans requires a maximum weight of 35 kgs.

Moreover Nexans doesn't agree to receive pads which are put on the side of the box.

This complaint is valid for all widths

Actions demandées au client

#### 3) Actions Conservatoires Sur Le Process

#### II. EVALUATION ET ACTIONS

Echantillons/Photos Reçus	No						
Date							
Responsable Processus	Sylviane Carras						
Responsable Action	trimmer						
Réclamation justifiée?	Yes	Retour marchandise		Destruction marchandise			
Commentaires							
Copy of TRD684D has bee	n attached to Scapa	complaints system as co	onfirmation for this action.				
1) Analyse							
Customer is complaining in respect of SFR10/103 pads due to (a) pads being packed on their side in the individual carton; and (2) individual cartons weighing more than 35kg.  Photos provided by the customer confirm the concern and have been circulated within Scapa.							
Auteur	Philip Ward		Date	30 Jun 2011			
				20.000			
2) Causes							
Customer specific instruction	on TRD684 did not co	ontain these requirement	S.				
Auteur	Philip Ward		Date	30 Jun 2011			
3) Solutions Possibles							
Update customer specific instruction TRD684 to state (a) do not pack coils on their side and only pack coils flat; and (b) maximum individual carton weight to be no more than 35kg.							
Auteur	Philip Ward		Date	30 Jun 2011			
4) Mise En Place Actions Correctives Permanentes							
Customer specific instruction TRD684 was amended to state (a) do not pack coils on their side and only pack coils flat; and (b)							
maximum individual carton weight to be no more than 35kg. This document was re-issued to Production and will be available for							
use on the Conversion and Packing plant for SFR 10/103 pads made after 01/07/2011.							
Auteur	Philip Ward		Date	30 Jun 2011			
Date Estimée	30 Jun 2011		Date De Mise En Place	30 Jun 2011			
Date De Validation	30 Jun 2011						

#### 5) Validation Des Actions Correctives

Scapa has implemented the above corrective actions.

Customer specific instruction TRD684 was amended to state (a) do not pack coils on their side and only pack coils flat; and (b) maximum individual carton weight to be no more than 35kg. This document was re-issued to Production and will be available for use on the Conversion and Packing plant for SFR 10/103 pads made after 01/07/2011. Relevant Production Operatives informed verbally by QA & Production Supervision.

Copy of TRD684 has been attached to Scapa complaints system as confirmation for this action.

6) Actions Préventives							
System update: customer	specific instruction TRD684 re-issued on 01/07	7/2011					
Other items potentially affe	ected: above corrective action will cover all SFI	R10/103 pads supplied to Nexa	ans France, converted				
and packed after 01/07/2011.							
Monitoring: QA to random check SFR10/103 packing activity for an interim period.							
Auteur	Philip Ward	Date	30 Jun 2011				
Date Estimée	30 Jun 2011	Date De Mise En Place	30 Jun 2011				
Date De Validation	30 Jun 2011						
7) Mise à Jour Docui	mentation						
(a) MSR							
Commenté?	No						
Référence		Date					
(b) Révision logigrammes	plans de surveillance/instructions de fabricatio	n et de contrôle					
Commenté?	Yes						
Référence	TRD684	Date	01 Jul 2011				
(c) Révision AMDEC							
Commenté?	No						
Référence		Date					
(d) Spécification client							
Commenté?	No						
Référence		Date					

Date

30 Jun 2011

## 8) Félicitations à Toute L'équipe

Philip Ward

Auteur