TRD 684 Issue D dated 01/07/2011

## P1310 (SFR10/103) - Nexans France, Paillart & Lyon sites

Reason for Issue: Addition of Lyon site (account 105188). Addition of statement for packing of coils and maximum carton weight (following complaint 100579).

Replaces: TRD 684 issue C dated 18/10/2010 and TRD 686 issue A dated 10/06/2011.

REASON FOR TR:

Reason 1: CUSTOMER SPECIFICATION

Reason 2: JOINT FREE/COILS IN BAGS/CARTON LABELING

PRODUCTS AFFECTED: P1310 SFR10/103

CUSTOMER ACCOUNTS: 105187 Nexans France (Paillart) 105188 Nexans France (Lyon)

**RELATED SPECIFICATIONS:** FRPA0251 Ed 03

#### SPECIAL PROCESS REQUIREMENTS:

#### MANUFACTURE:

All coils must be JOINT FREE

- Each individual coil must have label applied to the inside of the core stating the following:
  - Product Name (SFR10/103)
  - Supplier Name (Scapa)
  - Batch Number
  - Customers Order Number
- All coils to be packed in plastic bags
- Pack wrapped coils in cartons to fit the OD of the coils. No mixed sizes in cartons. Pack wrapped coils **flat in carton** and **insert air pillows in the corners of the carton** to minimise movement of coil during transportation.
- Do NOT pack coils into the carton on their side.
- Each individual carton to weigh no more than 35kg

\_\_\_\_\_\_

# MARKING AND LABELLING:

- Carton Label additional: please ensure customers order number and nett weight of the carton are stated on the carton label
- Pallet Marking please ensure Gross Weight of the pallet and Nett weight of the pallet are clearly marked.

-----

INSPECTION TIME REQUIRED FOR RELEASE: 24 hours

To Doros

-----

### Approval

Originated, approved & issued by:

Quality Assurance Officer Scapa UK Limited